

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 419700

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 34 only, T31-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page(s) 8170)

Set a Cedar post 4 ft. long, 4" sq., 24" in the ground and mkd. S34 ¼ on W. face for the ¼ sec. cor., from which
A Fir 20" dia., bears S.20°W., 46 lks. dist. mkd. S34 ¼ S BT.
A Fir 10" dia., N.20°W., 24 lks. dist. mkd. S34 ¼ BT.

GLO Resurvey by Fred Mensch and Gerald A. Sorrels, Surveyors under Special Instructions, Group #35, dated Dec. 22, 1916 - (DCSO records Vol. 29 Page(s) 12190)

Intersect at the ¼ cor. of sec. 34 only, which is a Cedar post, firmly set, mkd. and witnessed as described by the surveyor general. I perpetuate this cor. as follows: alongside the old cor.
Set an Iron post 3 ft. long, 1" dia., 26" in the ground for ¼ cor. of sec. 34, T31S R9W only with brass cap marked
¼ S 34
1917
from which
A Fir 12" dia., bears N.57°E., 27 lks. dist. mkd. ¼ S34 BT (New BT)
A Fir 14" dia., bears N.27°W., 23 lks. dist. mkd. ¼ S34 BT (Old BT)

Survey by Lorne Swearingen - For: Robert Dollar Co. - Milner Larson - Nov. 16, 1960 - C.S. File 51/68-9

Corner destroyed during logging operations.
Orig. 14" Fir N.27°W., 15.2 ft. is a stump with orig. scribing visible.
Orig. 12" Fir N.57°E., 17.8 ft. is a windfall deteriorated so badly all evidence of scribing is gone.
Marked the corner with a 7/8" x 30" hex drill steel, driven 20" in the ground from which I referenced:
12" I.Cedar N.15°E., 92.2 ft. scribed S34 ¼ S 4186 BT.
Since all of sec. 34 has been logged and the remaining trees are either too small or I felt they were not windfirm, I mkd.
An 8" Fir S.32½°E., 24.9 ft. scribed S34 ¼ S 4186 BT.
This tree is in sec. 3, T32S R9W W.M. and the ¼ corner is not common to this section, but I felt that this tree would best perpetuate the corner as it should be wind firm and not cut when section 3 is logged.

(Cont. Next Page)

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 419700

PRIMARY CORNER DESCRIPTION So. ¼ corner for Sec. 34 only, T31-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Milner L. Larson - For: Robert Dollar Co. - Nov. 18, 1965 - C.S. File 51/68-9

Re-established by Swearingen in 1963. Of the two BTs established the

12" I.Cedar N.15°E., 92.2 ft. is in good condition.

8" Fir S.32½°E., 24.9 ft. was destroyed in a clear cut logging operation.

New BT - 10" Fir S.17½°W., 88.0 ft. scribed ¼ S RE 3642 BT. (Although this tree is again in sec. 3, T32S R9W, I felt it best suited the purpose.)

Tony Hostetter - For: Plum Creek Co. - Jan. 22, 2009 - C.S. File 65/66-15

Found - 7/8" hex drill steel as set by Swearingen from orig. BTs in 1960

24" cedar, face evident, (New tag) BT marked by Swearingen in 1961, bears N.15°E., 92.2 ft. to center.

20" fir, face evident, (New tag) BT marked by Larson in 1965, bears S.17½°W., 88.0 ft. to center.

New BTs- 11" Fir, scribed "S34 ¼ BT" BT tag, bears N.33°E., 7.4 ft. to 20D spike placed in root collar below scribing.

10" fir, scribed "S34 ¼ BT" BT tag, bears S.19°W., 2.1 ft. to 20D spike placed in root collar below scribing.

BLM dependent resurvey by Kevin G Mulder, Cadastral Surveyor, under Group No. 2862; Surveyed Nov./Dec. 2016 - (DCSO records Vol. 59 Page(s) 23582-3)

The ¼ sec. cor. of sec. 34 only, perpetuated by Swearingen, in 1960, further perpetuated by Larson, in 1965, and further perpetuated by Hostetter, in 2009; monumented with a hexagonal drill steel, 7/8" across top, flat to flat, firmly set, projecting 6" above the ground, from which the remains of an original bearing tree

A badly decayed fir stump, size indeterminate, bears N.27°W., 15.2 ft., with illegible scribe marks visible on exposed face.

and a bearing tree mkd. by Swearingen

A cedar, 30" dia., bears N.14¼°E., 92.2 ft., with a healed blaze.

and a bearing tree mkd. by Larson

A fir, 24" dia., bears S.16°W., 88.2 ft., with a healed blaze.

continued next page

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 419700

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 34 only, T31-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and bearing trees mkd. by Hostetter
A fir, 11" dia., bears N.29¼°E., 8.3 ft., with a healed blaze and a spike in the face.
A fir, 10" dia., bears S.16°E., 3.4 ft., with a healed blaze and a spike in the face.

At the corner point
Set a stainless steel post, 28" long, 2½" dia., 23" in the ground, directly over the hexagonal drill steel, with brass cap mkd.

T31S R9W
¼ S34
T32S R9W
2016

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Note: No remaining evidence of the iron post monument as established by Mensch and Sorrels in 1917 was found.