

34

Subdivisions of T. 21 S., R. 5 W.
as surveyed by D. W. Applegate, under
Contract No. 351, dated May 11, 1880

CHAINS

Found the cor. of sec. 19, 20, 29 and 30 entirely obliterated by Fire.

Began at the $\frac{1}{2}$ sec. cor. bet. secs. 29 and 30.

Thence North, 40.00 chs., and re-established the cor. of Secs. 19, 20, 29 and 30, by setting a stone, 2 ft x 6 x 8 ins. with trench, etc. No bearing trees in reach.

Found the description of country to correspond with notes furnished by Surveyor General.

Found the bearing trees for cor. of Sec. 24, 25, 19 and 30, still standing, but post rotted away.

Re-established cor. by building a stone mound at the point indicated by field notes furnished, etc.

Va. 21*E.

West, on random bet. secs. 19 and 30.

81.43 To point 41 lks. N. of the cor. of sec. 24, 25, 19 and 30.

North, $89^{\circ}42'E.$, on a true line bet. secs. 19 and 30.

Va. 20*E.

2.40 Creek, 3 lks. wide, course S.

12.50 Leave timber, enter Burnt region.

21.45 Creek, 2 lks. wide, SE.

41.43 Set $\frac{1}{2}$ sec. cor. post, from which

A Fir, 18 ins. dia., bears $N.88^{\circ}E.$, 25 lks. dis.

A Fir, 24 ins. dia., bears $S.63^{\circ}W.$, 72 lks. dis.

45.50 Top of ridge, NW. and SE.

56.90 Creek, 1 lk. wide, course North.

75.00 Creek, 2 lks. wide, course North.

81.43 Intersect cor. of sec. 19, 20, 29 and 30.

Land, rolling.

Burnt woods.

Soil, 2nd rate; good pasture.

June 24, 1880