

Resurvey of South Bdy. of sec. 36, T. 22 S., R. 9 W.

CHAINS

Practically agreeing with notes furnished by the U. S. Surveyor General.

Land, mountainous. 42.60 chs.

Soil, second rate.

Timber, Fir, Hemlock, Cedar, Maple and Alder.

Undergrowth, dense, vine-Maple, Hazel, Fir, Hemlock and Arrow wood. 42.60 chs.

April 1, 1895.

Resurvey of Subdivisions of T. 22 S., R. 9 W.  
Same Deputy and Contract.

Commenced at the corner to secs. 7, 8, 17 and 18.

Thence, 1 run, South, between secs. 17 and 18.

Va. 20°E.

40.00 After diligent search, could not find the  $\frac{1}{4}$  sec. corner.

Pass over spur.

45.25 A creek, 8 lks. wide, Course SW.

Pass over spur.

68.00 A creek, 5 lks. wide, Course W.

77.20 A creek, 2 lks. wide, Course NW.

84.13 To a point 21 lks. E. of the corner to secs. 17, 18, 19 and 20, which is a post, 2 feet above ground, 4 ins. square, marked T. 22 S., S. 17 on the NE., R. 9 W., S. 20 on the SE., S. 19 on the SW., and S. 18 on the NW. faces with 3 notches on the South and 5 notches on the East edges, from which,

A Maple, 16 ins. diam., bears N.40°E., 41 lks. dist.

Marked T. 22 S., R. 9 W., S. 17 B. T.

A Maple, 14 ins. diam., bears S.55°E., 75 lks. dist.

Marked T. 22 S., R. 9 W., S. 20 B. T.

A Fir, 32 ins. diam., bears S.30°W., 45 lks. dist.

Marked T. 22 S., R. 9 W., S. 19 B. T.