

Subdivisions of T. 23 S., R. 10 W.

CHAINS

An alder, 6 ins. diam., bears N.87*E., 25 lks. dist.

Marked T 23 S R 10 W S 15 B T

A fir, 18 ins. diam., bears S.10*E., 57 lks. dist.

Marked T 23 S R 10 W S 22 B T

A fir, 12 ins. diam., bears S.19*W., 59 lks. dist.

Marked T 23 S R 10 W S 21 B T

An alder, 8 ins. diam., bears N.70*W., 13 lks. dist.

Marked T 23 S R 10 W S 16 B T

Land, mountainous

Soil, 3rd rate

Timber, mostly 2nd growth fir with some hemlock and alder

Undergrowth, small fir, hemlock, alder, salal and huckleberry.

Land, mountainous, heavily timbered or covered with dense undergrowth, 80.00 chs.

June 4, 1906.

Cor. of secs. 15, 16, 21 and 22

Thence I run

S.89*51'E., on a random line bet. secs. 15 and 22.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

75.53 Intersect N. and S. line, 1.57 chs., N.0*12'W. of cor.

of secs. 14, 15, 22 and 23, which is a fir post, 4 ins. sq., 12 ins. above ground, badly decayed, marked and witnessed as described by the Surveyor General.

I destroy old post and obliterate all marks referring to secs. 15 and 22 on bearing trees, and at the same point

Set a new fir post, 3 ft. long, 4 ins. sq. 24 ins. in the ground, marked

T 23 S S 14 on NE., and

R 10 W S 23 on SE. face, with 3 notches on S., and 2 notches on E. edge.

The intersection being beyond allowable closing limits.