

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 24 S., R. 4 W.
General Description

CHAINS

destroyed some of the timber, there is a moderate growth of grasses. No settler is living on any of this now surveyed land although there appears to be some land in sec. 14 which may induce settlement.

Oscar F. Thiel

U.S. Deputy Surveyor

Supplemental Notes of Subdivisions of T. 24 S., R. 4 W.
Same Deputy and Contract

From the $\frac{1}{4}$ sec. cor. bet. secs. 11 & 12 which is a Fir Post 24 ins. above ground firmly set, but badly decayed, marked and witnessed as described by the Surveyor General and which I replace at the same point, by setting a Fir Post, 3 ft. long 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on W face, having destroyed all remains of the old post.

I run

N.0*1*W., on a Random line bet. secs. 11 & 12

40.10 Intersect E & W line 8 lks. West of cor. of secs. 1, 2, 11 & 12

Thence I run

S.0*2*W., on true line bet. secs. 11 & 12

17.85 Through heavy timber, Fir; descend SE slope of mountain A Branch 8 lks. wide, course S.30*W., 300 ft. below sec. cor.

Began ascent of W slope of a mountain spur

22.60 Top of Spur, bears W & E, 250 ft. above branch; begin steep descent of S slope

29.50 The descent moderates

40.10 The $\frac{1}{4}$ sec. cor., 450 ft. below $\frac{1}{4}$ sec. cor.

Land Mountainous

Soil, gravelly, 4th. rate

Timber, Fir, Cedar, Yew, Maple

Mountainous or heavily timbered land, 40.10 chs.

April 19, 1897