

Subdivisions of T 24 S., R 7 W., W.M.

CHAINS		
	West bet. secs. 8 and 17.	
		Va. 19*E.
2.50	Enter brush, course N and S.	-25
23.70	Branch, 2 lks. wide, course SW.	-200
24.95	Branch, 2 lks. wide, course S.	-10
40.00	Set $\frac{1}{2}$ sec. post, from which	+200
	An Oak, 40 ins. diam., bears S.85*E., 60 lks. dist.	
	An Oak, 40 ins. diam., bears N.10*W., 32 lks. dist.	
60.50	Summit of ridge, course N and S.	+400
80.00	Set post, cor. secs. 7, 8, 17 and 18, from which	-100
	A Fir, 15 ins. diam., bears S.87*E., 25 lks. dist.	
	A Fir, 12 ins. diam., bears N.20*E., 12 lks. dist.	
	A Fir, 24 ins. diam., bears N.16*W., 28 lks. dist.	
	A Fir, 24 ins. diam., bears S.45*W., 21 lks. dist.	
	Land hilly, about $\frac{3}{4}$ brushy openings, balance timbered with fir and cedar.	
	Soil 2nd rate.	
		July 11th, 1857

Exterior lines of T. 24 S., R 8 W., W.M. as surveyed by Henry L. Chandler, U.S. Deputy Surveyor, under Contract No. 619, dated June 5, 1893.

I commence at the cor. to secs. 19, 24, 25 and 30, on the East bdy of Tp., which is a post, so badly decayed that the marks are almost entirely obliterated, from which

A Cedar, 12 ins. diam., bears S.70*E., 25 lks. dist.

The other bearing trees described in notes furnished me are all destroyed.

I set a new post, 4 ft. long, 4 ins. sq., 24 ins. in the ground for cor. to secs. 19, 24, 25 and 30, marked

T 24 S S 19 on NE.

R 8 W S 30 on SE.

R 7 W S 25 on SW and

S 24 on NW faces with 2 notches on S and 4 notches on N edges, from which