

Retracements of South Boundary T. 24 S., R. 8 W.

CHAINS

31.00 Creek, 5 lks. wide, course S.80*W.

38.90 Creek, 15 lks. wide, course SW.

39.40 Fall, 5 lks. N. of the $\frac{1}{4}$ sec. cor. bet. Secs. 6 and 31, (which is a post, marked and witnessed as described by the Surveyor General and which I now change to refer to Sec. 31, T 24 S., R. 8 W., only). The true course of this line is S.89*56'W., and the distance is 39.40 chs.

At this corner
Ascend long side of steep ridge, in heavy timber and brush.

61.35 Fall, 5 lks. S. of the cor. of Tp. 24 S., R. 8 W., which is a post, nearly decayed, bearing trees in good condition, otherwise marked and witnessed as described by the Surveyor General. I re-establish this cor. as follows: At this exact point where old Tp. cor. stood, I set a new Cedar post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for cor. of Tp. 24 S., Rs. 8 and 9W., marked T. 24 S R 8 W S 31 on N. and W. edges, from which

A Cedar, 10 ins. diam., bears N.20*E., 30 lks. dist., marked T 24 S R 8 W S 31 B T.

A Fir, 60 ins. diam., bears N.60*W., 24 lks. dist., marked T 24 S R 9 W S 36 B T.

I destroy all markings on old bearing trees to the SE. and SW.

The true course of this line is N.89*44'W., and the length is 21.95 chs.

Land, mountainous.

Soil, 2nd and 3rd rate.

Dense undergrowth, little fir, hemlock and vinamaple.

Timber, Fir, Hemlock and Cedar.

Mountainous land, covered with heavy timber and exceptionally difficult to survey. 61.35 chs.

June 20th, 1911.