

Retracement of Subdivision of T. 24 S., R. 9 W.

CHAINS

Land, mountainous.

Soil; 3rd rate.

Timber, fir, hemlock and cedar.

Undergrowth, vinemaple, huckleberry and salal.

 Land, mountainous, heavily timbered or covered with
dense undergrowth. 76.14 chs.

Sec. 10 not closing within limits, after retracing my
work and finding it correct, in order to locate the
error I proceed as follows:

At cor. now common to secs. 11 and 14 only, heretofore
described.

The old post is in a good state of preservation, but the
bearing tree on the NE. being uprooted, I mark a new
one in place of it, as follows: from the corner,

A fir, 16 ins. dia., bears N.48°E., 48 lks. dist.
mkd. T 24 S R 9 W S 11 B T

Thence I run

North, on a blank line on W. Bdy. of sec. 11.

Over mountainous land through heavy timber and dense
undergrowth.

39.39 The $\frac{1}{4}$ sec. cor. which is a post marked and witnessed as
described by the Surveyor General, bears West, 23
lks. dist.

The true bearing of this line is therefore N.0°20' W.

The old post being greatly decayed, I destroy same and at
the same point, set a fir post, 3 ft. long, 4 ins. sq.,
24 ins. in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S 11 on
E face.

Thence, I continue my line from the $\frac{1}{4}$ sec. cor.

North, on a blank line.

24.00 Lake Creek, 70 lks. wide; course W.

40.08 The cor. of secs. 2, 3, 10 and 11 which is a post marked and
witnessed as described by the Surveyor General, bears
West, 46 lks. dist.