

Subdivisions of T. 25 S., R. 6 W., W. M.

CHAINS	<p style="margin: 0;">A fir, 48 ins. diam., bears N.50*E., 11 lks. dist. A fir, 8 ins. diam., bears S.55*E., 50 lks. dist. 44.00 A pond, 60 lks. by 200.</p> <p style="margin: 0;">55.00 Begin steep ascent.</p> <p style="margin: 0;">78.50 Top of ridge, course N.10*E.</p> <p style="margin: 0;">80.10 To sec. cor.</p> <p style="margin: 0;">Land, East part; hilly, brushy, 2nd and 3rd rate. West part; steep mountainous, rocky broken, 3rd rate. Timber, Fir, Oak, Laurel and Cedar. Underbrush, same. September 8, 1877.</p>	+1500
<p>The land along the foot of the mountain and to the East, is a continuation of benches and ridges, generally covered with a thick undergrowth of Fir and other brush. The timbers were good, but have been generally culled out by settlers until but the refuse remains. The mountain is too steep and precipitous to be any value.</p>		
<p>East Bdy. of T. 25 S., R. 7 W., W. M., as surveyed by Wm. P. Heyden, Deputy Surveyor, under Contract 656, dated May 21, 1896.</p>		
<p>At the cor. of secs., 1, 6, 7 and 12, T. 25 S., Rs. 6 and 7 W., which is a post, marked and witnessed as described by the Surveyor General.</p> <p>The post being badly decayed in its place, I set a new Fir post, 4 ft. long, 5 ins. sq., 36 ins. in the ground marked T 25 S S 6 on NE., R 6 W S 7 on SE., R 7 W S 12 on SW. and S 1 on NW. faces, with 5 notches on S. and 1 notch on N. edges.</p> <p>The original witness trees being in good condition, I make no change.</p> <p>Thence I run</p> <p>North, on a random line bet. secs. 1 and 6.</p> <p style="text-align: right;">Va.20*03'E.</p>		
40.00	Set tem. $\frac{1}{4}$ sec. cor.	