

41

Retracement of East Bdy. T. 25 S., R. 9 W.

CHAINS
101.40

Intersect S. bdy. of T. 24 S., R. 9 W., 22.74 chs. N. 89°56'W. of cor. for T. 24 S., Rs. 8 and 9 W., previously described. The true course and distance of this line, from the old closing cor. is North, 26.55 chs.

At point of intersection, I set a cedar post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for closing cor. of T. 25 S., Rs. 8 and 9 W., marked C C on S., T 25 S R 8 W S 6 on E., T 25 S R 9 W S 1 on W. faces; with 6 grooves on E., S. and W. faces; from which

A cedar, 60 ins. diam., bears S.86°W. 11 lks. dist.
marked T 25 S R 9 W S 1 B T

A cedar, 12 ins. diam., bears S.60°E. 78 lks. dist.
marked T 25 S R 8 W S 6 B T

Land mountainous.

Soil; 2nd and 3rd rate

Timber, heavy fir, hemlock and alder

Dense undergrowth, little fir, hemlock and rhododendron.

Mountainous land, covered with heavy timber and dense undergrowth and exceptionally difficult to survey
26.55 chs.

NOTE:-

There appears to be an unsurveyed strip of land, or an hiatus, bet. Tps. 24 and 25 S., Rs. 9 W., 26.55 chs. wide lying to the west of this line.

July 21, 1911

Retracement and Resurvey of Subdivisional Section Lines T. 25 S., R. 8 W. As surveyed by Morris Wygant, Compassman for Zachariah M. Derrick U. S. Deputy Surveyor, Under Contract No. 779, dated Feb. 7, 1908

At the Cor. of Secs. 9, 10, 15 and 16, which is an old post, badly decayed, but markings plain; found bearing trees as described by the Surveyor General, but all are badly decayed and burnt.

I reestablish this cor. as follows:

At the exact cor. point where old cor. stood, I set a cedar post, 3 ft. long, 4 ins. sq. 24ins. in the ground