

~~778~~
County Surveyor's Record, Douglas County, Oregon

Resurvey of Subdivisional Lines, T. 26 S., R. 2 W.

CHAINS

I destroy the corresponding cor. of the rejected revision survey and marks on bearing trees

Land, mountainous

Soil, stony clay loam, 3rd rate

Timber, fir, cedar and hemlock

Undergrowth, hemlock, rhododendron, vine maple and huckleberry

N.1*12'E., resurveying the line bet. secs. 22 and 23

Over mountainous land, through dense timber and undergrowth

Across level bench

6.80 Descend Steep NE slope

14.05 Creek, 1 lk. wide, course NW, descend NW slope

18.80 Creek, 1 lk. wide, course NW

29.55 Ravine, course NE, descend NE slope

42.62 Intersect the original $\frac{1}{4}$ sec. cor., established by Deputy McQuinn in 1883 and reestablished by Deputy Gibb in 1909, which is a granite stone, 5x10x6 ins. above ground, firmly set, marked as described by the surveyor general and witnessed by the original bearing trees of the McQuinn survey. The bearing tree on the east is now a dead and broken stub. I now perpetuate this cor., as follows:
Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, 1 lk. W. of cor., with brass cap marked

$\frac{1}{4}$
S22 | S23
1916

Note: This $\frac{1}{4}$ sec. cor. is now intended to refer to Sec. 23 only

from which

A hemlock, 14 ins. diam., bears S.15*E., 44 lks.

dist. Marked $\frac{1}{4}$ S 23 B T

A maple, 18 ins. diam., bears N.89*W., 11 lks. dist.

Marked $\frac{1}{4}$ S 22 B T (Orig. B.T.)

I destroy the corresponding cor. of the rejected revision survey and marks on bearing trees.

Thence

N.0*15'E., continuing the measurement