

Exteriors of T. 29 S., R. 4 W.

CHAINS		
7.00	Top of spur, C. S. & N. Leave Oak openings, enter Fir timber, begin descent.	+80
18.00	A branch, 2 lks. wide, C. S. 30°E. oak timber with	-200
23.00	Leave inclosure, begin ascent, through/heavy undergrowth.	
30.00	Top of spur, C. SW., begin descent.	+60
33.00	A run, C.SW., begin ascent.	-30
36.00	Top of spur, C. S. 60°W.	+50
38.72	The cor. to Tps. 29 and 30 S., Rs. 3 and 4 W. Land, hilly, very much broken. Soil, gravelly, 3rd rate. Timber, Fir, Oak, Cedar, Laurel. Undergrowth, mostly young Oaks, Laurels and Fir, also Hazel.	-10
38.40	West, on a Random line along South boundary of Sec. 35. Va. 19°E.	
77.22	<p>½ sec. cor. bears N. 84 lks.</p> <p>Intersect N. &amp; S. line 139 lks. S. of cor. to Secs. 34 and 35.</p> <p>The post set for this corner is gone but all the bearing trees described in the field notes of original survey are standing. I restore this corner by setting a Cedar post 4½ ft. long, 4 ins. sq., 24 ins. in the ground, marked:</p> <p style="padding-left: 40px;">T29S R4W on N. face, S35 on E. face, S34 on W. face, and 2 notches on E., and 4 notches on W. faces, from which</p> <p style="padding-left: 40px;">A Bl. Oak, 18 ins. diam., bears N. 80°E., 60 lks. dist., mkd.: T29S R4W <del>on</del> S35 BT.</p> <p style="padding-left: 40px;">A Bl. Oak, 12 ins. diam., bears N. 57°W., 38 lks. dist., mkd.: T29S R4W S34 BT. This is the old bearing tree in Sec. 34., which I remark, as the old marks are overgrown.</p>	