

Resurvey of Subdivisions, T. 30 S., R. 1 W.

CHAINS

40.50 Intersect corner of secs. 10, 11, 14 and 15, which is a decayed post, 20 ins. above ground, marked and witnessed as described by the surveyor general.

The course of this line is S.89°34'E. and the length is 40.50 chs.

Land, mountainous.

Soil, clay, loam and stony, second and third rate.

Timber, red fir, sugar and yellow pine, oak; undergrowth, fir, oak, arrowwood, hazel.

Mountainous or heavily timbered land or land covered with dense undergrowth, 81.25 chs.

August 11: The line bet. secs. 8 and 9 being out of limits with the reported length of the line bet. secs. 7 and 8, I commence at the corner of secs. 7, 8, 17 and 18, previously described

Thence, I run

North, bet. secs. 7 and 8.

Over mountainous land through scattering timber and dense undergrowth.

Desc. gradually along NW. slope.

30.50 Enter river bottom.

31.00 Enter swamp.

38.25 Leave swamp.

Enter heavy timber, bears NE. and SW.

40.45 Intersect the  $\frac{1}{4}$  sec. corner which is nearly obliterated.

The old corner which was a post has disappeared. Both bearing trees have fallen and decayed, though the stumps are still standing with marks yet distinguishable. I destroy the old marks and re-establish the corner in its original position as follows:

Set an ironstone 16x12x4 ins. 11 ins. in the ground for  $\frac{1}{4}$  sec. corner, marked  $\frac{1}{4}$  on W. face; from which

A hemlock, 12 ins. diam., bears N.49°E., 18 lks.