

## Retracements of Subdivision Lines of T. 30 S., R. 2 W.

CHAINS

A Yellow Pine, 8 ins. diam., bears S.50°E., 16 lks. dist. marked T 30 S, R 2 W, S 22 B T.

A Fir, 10 ins. diam., bears S.54°W., 10 lks. dist. marked T 30 S, R 2 W, S 21 B T.

A Madrone, 8 ins. diam., bears N.25°W., 37 lks. dist. marked T 30 S, R 2 W, S 16 B T.

Thence I run

North between secs. 15 and 16.

Over mountainous land, heavily timbered and covered with dense undergrowth.

Ascend S. slope.

5.25 Ridge bears Nw. and SE.

Gradually descend along E. slope.

38.65 Creek, 2 lks. wide, course E.

40.50 The  $\frac{1}{4}$  sec. cor. partially obliterated, bears W 49 lks. dist.

The cor. tree is dead and ready to fall

I re-establish the cor. in its original position as follows:

I uproot the dead cor. tree and in the cavity set a basalt stone 15x10x6 ins., 10 ins. in the ground, for  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  on W. face, from which,

A Fir, 18 in. diam., bears S20°E., 5 lks dist. marked  $\frac{1}{4}$  S 15 B T.

A Fir, 20 ins. diam., bears N.75°W., 16 lks. dist. marked  $\frac{1}{4}$  S 16 B T.

The course of this line is N.0°42'W., and the distance is 40.50 chs.

Land, mountainous.

Soil, clay and stony, second and third rate.

Timber, Fir, Hemlock, Cedar.

Undergrowth, Hemlock, Fir Hazel Vine-Maple

Mountainous or heavily timbered land or land covered