

Resurvey of Exterior Lines of T. 30 S., R. 4 W.

CHAINS

North on a random line between secs. 25 and 30.

Va. 19\*30'E

37.79  $\frac{1}{4}$  sec. cor. bears W. 74 lks. dist.

77.07 Intersect N. boundary of sec. 25, 33 lks. W. of cor. to sec.s 25, 24, 30 and 19. The post, set for this cor. is lying down, decayed, but all four bearing trees are still standing and easily identified. I restore this cor. by setting a W. Oak post  $4\frac{1}{2}$  ft. long 4 ins. sq., 24 ins. in the ground marked, T 30 S S 19 on NE R 3 W S 30 on SE R 4 W S 25 on SW S 24 on NW faces, with 4 notches on N and 2 notches on S edges, from which

A Laurel, 14 ins. diam., bears N.40\*E., 33 lks. dist., marked T 30 S R 3 W S 19 B T.

A Laurel, 24 ins. diam., bears S.45\*E., 40 lks. dist., marked T 30 S R 3 W S 30 B T.

A Laurel, 10 ins. diam., bears N.50\*W., 19 lks. dist. marked T 30 S R 4 W S 24 B T.

A Laurel, 14 ins. diam., bears S.47\*W., 36 lks. dist., marked T 30 S R 4 W S 25 B T.

All of which I remark, the old marks being overgrown and dim.

Thence

S.0\*29'W., on true line between secs. 25 and 30.

Va. 19\*20'E

Ascend in timber, heavy underbrush.

6.50 Top of spur, course East and West, begin descent.

+50

10.00 Enter Oak openings.

13.00 Heavy thicket of small W. Oak.

15.50 A dry branch, course SW. Begin ascent.

-75

28.15 Intersect a post, marked T 30 S R 4 W S 24 on N. face.

39.28  $\frac{1}{4}$  sec. cor. post is gone but both bearing trees are