

## Resurvey of Exteriors of T. 30 S., R. 4 W.

CHAINS

33.00 Va. 18\*25'E

38.10 The cor to secs. 12, 13, 7 and 18.

Land, mountainous all but the North 10 chs.

Soil, gravelly and 3rd rate, except North 10 chs. loam  
1st rate.

Timber, Fir mostly. A few Oaks, Ash, Maple and Cedar.

Undergrowth, principally young Fir.

North, on a random line between secs. 1 and 6.

Va. 19\*10'E

39.15  $\frac{1}{4}$  sec. cor., bears E. 70 lks.

78.15 Intersect N. boundary of sec. 1, 139 lks.

West, of cor. to secs. 31, 6, 1 and 36, Tps. 29 and 30  
S., Rs. 3 and 4W., the post, for this cor. is lying  
down, partially decayed, but all bearing trees are  
standing. I restore this cor. by setting a Cedar  
post, 4 $\frac{1}{2}$  ft. long, 4 ins. sq., 24 ins. in the ground,  
marked T 29 S S 31 on NE R 3 W S 6 on SE T 30 S S 1  
on SW R 4 W S 36 on NW faces, with 6 notches on each  
edge, from which

A B. Oak, 12 ins. diam., bears S.78\*E., 50 lks.

dist., marked T 30 S R 3 W S 6 B.T.

A B. Oak, 10 ins. diam., bears N.85\*E., 65 lks.

dist., marked T 29 S R 3 W S 30 B T.

A B. Oak, 10 ins. diam., bears S.40\*W., 59 lks.

dist., marked T 30 S R 4 W S 1 B T.

A B. Oak, 12 ins. diam., bears N.47\*W., 49 lks.

dist., marked T 29 S R 4 W S 36 B T.

These are the old bearing trees whose marks I renewed.

Thence.

S.1\*1'W., on true line between secs. 1 and 6.