

Subdivisions of T. 30 S., R. 4 W.

CHAINS	<p>to low gravel bar, making a westing of 25.14 chs., and northing 1.75 chs.</p>
30.94	Bar of river; go South 175 chs. to line.
34.50	Leave bar; begin ascent of bluff.
35.50	County road to Canyonville, course SW.; begin steep ascent.
40.78	<p>The Cor. to Secs. 14, 15, 22 and 23.</p> <p>Land, hilly.</p> <p>Soil, gravelly; 3rd rate.</p> <p>Timber, Oak, Fir, Pine and Alder.</p> <p>Undergrowth, mostly young Fir, Oak, Laurel, Greasewood, and Hazels.</p> <p>It is strange that the field notes of original survey do not mention the fact, that part of this line lies in the river.</p> <p style="text-align: right;">May 9, 1889.</p>
	Var. 18°35'E.
	North, on random line bet. Secs. 14 and 15.
33.45	$\frac{1}{4}$ Sec. Cor. bears East 54 lks.
79.06	<p>Intersect North Bdy. of Sec. 15, 119 lks. W. of Cor. to Secs. 10, 11, 14 and 15. The post set for this Cor. is gone; the bearing trees in Secs. 15, 10 and 14 are all standing. I restore this Cor. by setting an Oak post, 4 ft. long, 4 ins. sq., 24 ins. in the ground, marked T 30 S S 11 on NE., R 4 W S 14 on SE., S 15 on SW., S 10 on NW. faces, with 4 notches on S. and 2 notches on E. edges, from which</p> <p>A Fir, 18 ins. diam., bears S.31<math>\frac{1}{2}</math>*E., 54 lks. dist., marked T 30 S R 4 W S 14 B T.</p> <p>An Oak, 6 ins. diam., bears S.52<math>\frac{3}{4}</math>*W., 29 lks. dist., marked T 30 S R 4 W S 15 B T.</p> <p>An Oak, 8 ins. diam., bears N.41<math>\frac{1}{2}</math>*W., 59 lks. dist., marked T 30 S R 4 W S 10 B T.</p>

+25