

Subdivisions of T. 31 S., R. 5 W.

CHAINS

Timber, good. Fir and white cedar.

Land, poor, third rate.

Undergrowth, gooseberry bushes, and chaperille, very thick on top of Mt. Impossible to go through. Did not extend the line on the S. bdy., of sec. 8 as it runs along face of Mt., worthless, covered with dense mass of chaperille, not over 3 ft. high. Almost impossible to penetrate.

Soil, from face of Mt. covered with small broken rock.

Va. 20*E.

North, between sec. 7 and 8.

Up steep rocky point.

3.00 Descend hill, slopes N.80*W.

40.00 Marked a black willow for $\frac{1}{4}$ sec. cor., from which

A c Oak, 12 ins. diam., bears S.10*W., 25 lks.

A c Oak, 14 ins. diam., bears S.75*W., 15 lks.

Timber, fir, and cedar, good down spur slopes NE.

68.00 Cross branch, 8 lks. wide, flows N.60*W., evidence of mining on N. side of branch. See notice of Quartz Claim.

Ascend hill slopes S.50*W.

80.00 Marked a fir, 18 ins. diam., for cor. to secs. 5, 6, 7 and 8, from which

A fir, 12 ins. diam., bears N.10*W., 4 lks. dist.

A fir, 10 ins. diam., bears N.30*E., 3 lks. dist.

Bull Pine, 14 ins. diam., bears S.75*E., 22 lks.

W. cedar, 30x30 ins. diam., bears S.22*E., 46 lks.

Land, mostly steep Mt. side.

Soil, poor.

Timber, after the first 10 chs. good, fir and white cedar.

Undergrowth, briars.