

Retracement-Reestablishment of East Bdy. of T. 32 S., R 4 W.

CHAINS  
70.00

Spur, slope NE.; descend North slope.

75.25

Ravine, course East; along East slope.

79.79

Intersect the cor. of Secs. 19, 24, 25 and 30, which is a stone, firmly set, marked and witnessed as described by the Surveyor General. I now change this cor. to refer to Secs. 24 and 25 only and destroy the marks on the old bearing trees in Secs. 19 and 30.

Land, mountainous.

Soil, rocky, unfit for cultivation; fourth rate.

Timber, Fir.

Undergrowth, Manzanita, live Oak and Arrowwood.

October 21, 1913.

At the cor. of Secs. 13, 18, 19 and 24, I set off

11\*44'N.\*\*\*

Thence, I retrace South along East Bdy. of Sec. 24; at 38.87 chs. I fall 38 lks. East of the  $\frac{1}{4}$  Sec. cor. The discrepancy in closing of the lines of Sec. 19 being sufficiently accounted for, I discontinue the retracement at this point.

The  $\frac{1}{4}$  Sec. cor. of Secs. 19 and 24 is a stone, firmly set, marked and witnessed as described by the Surveyor General. I now change this cor. to refer to Sec. 24 only, and rewitnes as follows: From cor.

A Cedar, 20 ins. diam., bears S.55\*W., 37 lks. dist., marked  $\frac{1}{4}$  S. 24 B T.

A Fir, 10 ins. diam., bears N.44\*W., 44 lks. dist., marked  $\frac{1}{4}$  S 24 B T.

I destroy the marks on former bearing tree referring to Sec. 19.

Thence I run

N.0\*34'E. on a true line along the East Bdy. of Sec. 24.

Along East slope through dense timber and undergrowth.