

Retracement-Reestablishment of Subdivision Lines of T.32 S., R.3, W.

CHAINS

Timber, Fir, Sugar Pine, Pinon and Madrona.

Undergrowth, Lilac, Madrona and Rhododendron.

October 23, 1913.

At the cor. of Secs. 18 and 19.

Thence I retrace

North, between Secs. 17 and 18 and at 40.45 chs. intersect the $\frac{1}{4}$ Sec. cor.

Commencing again at the $\frac{1}{4}$ Sec. cor., I continue the retracement North, and at 39.76 chs. intersect the cor. of Secs. 7, 8, 17 and 18.

The cor. of Secs. 7, 8, 17 and 18 is a badly decayed post, marked as described by the Surveyor General.

The NW. bearing tree is still standing; the other trees have been destroyed by fire. I destroy this cor. and reestablish it in the same place as follows:

Set a granite stone, 18 x 10 x 8 ins., 12 ins. in the ground, for cor. of Secs. 7, 8, 17 and 18, marked with 4 notches on South and 5 notches on East edge, from which

A Fir, 10 ins. diam., bears N.39*E., 57 lks. dist., marked T 32 S R 3 W S 8 B T.

A Fir, 15 ins. diam., bears S.35*E., 80 lks. dist., marked T 32 S R 3 W S 17 B T.

A Fir, 8 ins. diam., bears S.5*W., 48 lks. dist., marked T 32 S R 3 W S 18 B T.

A Sugar Pine, 10 ins. diam., bears N.45*W., 20 lks. dist., marked T 32 S R 3 W S 7 B T.

Thence I run

South, on a true line, between Secs. 17 and 18.

Ascend NE. slope, through dense timber and undergrowth.

11.80 Spur, slopes East. Along East slope.

16.60 Creek, 1 lk. wide, course NE.

20.50 Spur, slopes SE.