

Retracement-Reestablishment of Subdivision Lines of T. 32 S., R. 3 W.

CHAINS

7, 12, 13 and 18, on the West Edy. of the Tp., previously described.

Thence I run

N.88°43'E. on a true line, between Secs. 7 and 18.

Ascend NW. slope, through dense timber and undergrowth.

1.80 Spur, slopes NE. Descend SE. slope.

18.80 Spur, slopes SE.

40.07 Intersect the $\frac{1}{4}$ Sec. cor. which is a badly decayed post, marked and witnessed as described by the Surveyor General I destroy this cor. and reestablish it in the same place as follows:

Set a slate stone, 18 x 10 x 8 ins., 12 ins. in the ground, for $\frac{1}{4}$ Sec. cor., marked $\frac{1}{4}$ on North face, from which

A Sugar Pine, 48 ins. diam., bears N.50°W., 24 lks. dist., marked $\frac{1}{4}$ S 7 B T.

A Cedar, 10 ins. diam., bears S.30°W., 16 lks. dist., marked $\frac{1}{4}$ S 18 B T.

I continue my measurements

S.84°25'E., on a true line, between Secs. 7 and 18.

44.50 Creek, 4 lks. wide, course NE. Ascend NW. slope.

63.00 Ridge, bears North and South. Descend SE. slope.

79.00 Creek, 3 lks. wide, course NE. Ascend NW. slope.

83.00 Spur, slopes North. Descend NE. slope.

83.99 Intersect the cor. of Secs. 7, 8, 17 and 18.

Land mountainous.

Soil, decomposed granite; third rate.

Timber, Fir, Sugar and Yellow Pine, Cedar and Madrona.

Undergrowth, Rhododendron, Snow Brush, Lilac and Arrow-wood.

October 26, 1913.