

## Subdivisions, T. 32 S., R. 4 W.

CHAINS	
47.25	Top of spur, slopes S., 50 ft. above last creek; desc.
50.85	Creek, 1 lk. wide, C. S., 50 ft. below spur; asc. spur.
54.00	Top of spur, slopes SW., 75 ft. above last creek; desc.
55.98	Creek, 1 lk. wide, C. SW., 50 ft. below last spur; asc.
	spur.
60.75	Top of spur, slopes SW., 100 ft. above creek; continue
	ascent on west slope of mountain.
69.75	To the corner of secs. 29, 30, 31 and 32, 75 ft. above last
	spur.
	Land, mountainous.
	Soil, third and fourth rate.
	Timber, Fir, Cedar, Madrona, Hemlock, Chinquapin, Yew
	and Alder.
	Dense undergrowth of Rhododendron, Ocean-spray, and
	Hazel.
	Land, mountainous, heavily timbered or covered with
	dense undergrowth 69.75 chs.
	Aug. 19, 1897.
	<hr/>
	The closing of the sectional correction line not being
	within required limits, I proceed as follows to find
	the error:
	From the corner of secs. 25 and 36, T. 32 S., R. 5 W.,
	which I reestablished Aug. 19, 1897, I run S. on a
	blank line, bet. secs. 36 and 31, and find this line,
	practically correct in measurement and alinement.
80.00	To corner of Tps. 32 and 33 S., Rs. 4 and 5 W., bearing
	trees all standing; post badly decayed; bearing trees
	agree with description of the surveyor general.
	I fail to find any closing corner described by the
	surveyor general as 370 lks. W. of the corner of Tps.
	32 and 33 S., Rs. 4 and 5 W., which I reestablished to
	refer to Tps. 32 and 33 S., R. 5 W., Aug. 20, 1897.