

Subdivisions, T. 32 S., R. 4 W.

CHAINS

A Fir, 48 ins. diam., bears S.57*E., 21 lks. dist., marked $\frac{1}{2}$ S B T.

This corner is on the SW Slope of spur, 100 ft. below top.

44.28 Creek, 1 lk. wide, C. S.20*W., 100 ft. below $\frac{1}{2}$ sec. corner; asc. mountain.

74.25 Top of mountain, 500 ft. above creek.

74.25 Leave green timber, bears NW $\frac{1}{2}$ and SE; desc.

80.09 To corner of secs. 10, 11, 14 and 15, 75 ft. below top of mountain.

Land, mountainous.

Soil, third and fourth rate.

Timber, fir, cedar, madrona, hemlock, chinquapin, maple and live oak.

Dense undergrowth of madrona, live oak, rhododendron, mountain-balm and manzanita.

Mountainous land, heavily timbered or covered with a dense undergrowth, 80.09 chs.

On Aug. 15, 1897, I retraced the S. bdy. of sec. 1, as follows:

From the established SW. corner of sec. 1, I ran North; 89*51'E., on a blank line on the S. bdy. of sec. 1.

40.03 To a point, 20 lks. N. of $\frac{1}{2}$ sec. corner, which is a post 20 ins. above ground, marked and witnessed as described by the surveyor general.

75.09 To a point, 39 lks. N. of the corner of secs. 1, 12, 6 and 7, which I reestablished from the bearing tree in sec. 6; the corner and all other bearing trees had been destroyed by fire.

Set a Fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for corner of secs. 6, 7, 12 and 1, marked

T 32 S S 6 on NE., R 3 W S 7 on SE., S 12 on SW., and

R 4 W S 1 on NW. faces, with 1 notch on N. and 5 notches on S. edges; from which,