

## Subdivisions, T. 32 S., R. 4 W.

## CHAINS

This corner is on the N. slope of spur, 100 ft. below top.

49.05 Creek, 1 lk. wide, C. N.30\*E., 100 ft. below  $\frac{1}{2}$  sec. corner.

69.47 Creek, 1 lk. wide, C. N.30\*E., 125 ft. below last creek; asc.

70;26 Intersect E. and W. line, 9.66 chs. S.89\*43'W. of corner of secs. 4, 5, 8 and 9, which is a post, 4 ins. sq., 24 ins. above the ground, marked and witnessed as described by the surveyor general.

Set a yew post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for a closing corner of secs. 8 and 9, marked C C T 32 S R 4 W on S., S 8 on W., and S 9 on E. faces, with 4 grooves on E. and 5 grooves on S. faces; from which

A Maple, 6 ins. diam., bears S.43\*E., 34 lks. dist., marked T 32 S R 4 W S 9 B T.

A Fir, 30 ins. diam., bears S.39\*W., 36 lks. dist., marked T 32 S R 4 W S 8 B T.

This corner is on left bank of and 20 ft. above creek. Land, mountainous.

Soil, third and fourth rate.

Timber, fir, hemlock, maple, madrona, yew and alder.

Dense undergrowth of hazel, rhododendron, vine-maple, mountain-balm, chinquapin and maërona.

Mountainous land, heavily timbered or covered with dense undergrowth, 70.26 chs.

September 6, 1897

The falling and measurement of the line bet. secs. 8 and 9 indicate a discrepancy in closing with the S. bdys. of secs. 4 and 5; I retrace said S. bdys. as follows, to locate the error:

From the corner of secs. 3 and 4, which I reestablished