

## County Surveyor's Record, Douglas County, Oregon

Retracement of the 7th Standard Parallel South  
through R. 8 W.

## CHAINS

Soil, loose, coarse, rocky loam, 3rd rate.

Timber, Fir, Pine and Madrona.

Undergrowth, Chinquapin, Live Oak, and Madrona.

---

N.89°18'W., on S. bdy. of Sec. 33.

Ascend 345 ft. over broken NE slope, through heavy green timber and dense undergrowth.

10.15 Spur, slopes N., descend 410 ft. over W. slope.

21.45 Branch, 3 lks. wide, course N., ascend 450 ft. over broken E. slope.

37.16 Find no evidence of the cor. post established for standard  $\frac{1}{4}$  cor. of Sec. 33.

True point for cor. established from original bearing trees.

At exact cor. point.

Set a porphyry stone, 15 x 10 x 6 ins., 10 ins. in the ground, for standard  $\frac{1}{4}$  cor. of Sec. 33, marked SC  $\frac{1}{4}$  on N face.

The old bearing trees being dead, I obliterate markings on same and take new bearing trees as follows:

A Fir, 20 ins. diam., bears N.36°E., 344 lks. dist., marked SC  $\frac{1}{4}$  S 33 B T.

A Fir, 24 ins. diam., bears N.52°W., 141 lks. dist., marked SC  $\frac{1}{4}$  S 33 B T.

Thence S.88°51'W.

Ascend 60 ft. over broken E. slope.

2.45 Spur, slopes NE., ascend 840 ft. over broken NE slope.

39.40 The standard cor. of Secs. 32 and 33, which is a granite stone, 12 x 8 x 4 ins. above ground, firmly set, marked and witnessed as described by the surveyor general.

The old bearing trees being in poor condition, I