

Dependent Resurvey of the Subdivisional Lines, T. 23 S., R. 6 W.

CHAINS

A cedar, 46 ins. diam., bears S. $34\frac{3}{4}^{\circ}$ W., 138 lks. dist.,
mkd. T23S R6W S34 BT.

A fir, 29 ins. diam., bears N. $47\frac{1}{4}^{\circ}$ W., 316 lks. dist.,
mkd. T23S R6W S27 BT.

Land, mountainous. Soil, sandy and clay loam. Timber, fir, hemlock, and cedar. Undergrowth, salal, poison oak, vine maple, alder, madrone, willow, and salmonberry.

From the cor. of secs. 25, 26, 35, and 36.

N. $89^{\circ}19'$ W., bet. secs. 26 and 35.

Descend 320 ft. over broken NW. slope, through logged and burned area, edge bears E. and W.

17.90 Spur, slopes S. 40° W.; desc. 71 ft. over SW. slope.

24.99 Spur, slopes S. 40° W.; desc. 41 ft. along N. slope.

32.695 Point for the $\frac{1}{4}$ sec. cor. of secs. 26 and 35, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2 ins. diam., 26 ins. in the ground, with brass cap mkd.

T23SR6W
 $\frac{1}{4}$ S 26
S 35
1957

from which

A hemlock, 8 ins. diam., bears N. 39° E., 120 lks. dist.,
mkd. $\frac{1}{4}$ S26 BT.

A fir, 6 ins. diam., bears S. 11° E., 58 lks. dist.,
mkd. $\frac{1}{4}$ S35 BT.

Descend 323 ft. over broken NW. slope.

34.92 Ravine, drains N. 70° W.; asc. 37 ft. along N. slope.

62.70 Road, improved, 40 lks. wide, bears N. 65° E. and S. 65° W.;
desc. 54 ft. over NW. slope.

65.39 The cor. of secs. 26, 27, 34, and 35.

Land, mountainous. Soil, clay loam. Timber, fir, hemlock, and cedar. Undergrowth, salal, vine maple, and salmonberry.

N. $7^{\circ}05'$ W., bet. secs. 26 and 27.

Over level land.

1.56 Yellow Creek, 20 lks. wide, course S. 75° W.; asc. 691 ft. over broken SE. slope.

32.23 Spur ridge, bears N. 60° W. and S. 60° E.; desc. 80 ft. along E. slope.

37.91 Point for the $\frac{1}{4}$ sec. cor. of secs. 26 and 27, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.