

County Surveyor's Record, Douglas County, Oregon

Remonumentation of Certain Original Corner Points, T. 25 S., R. 2 W.

CHAINS

A white pine, 14 ins. diam., bears N.  $87\frac{1}{2}^\circ$  E., 181 lks. dist., with scribe marks RE4079 S27 BT visible on unhealed double blaze.

A fir, 11 ins. diam., bears S.  $21^\circ$  E.,  $80\frac{1}{2}$  lks. dist., with scribe marks S34 RE4079 BT visible on unhealed double blaze.

A fir, 10 ins. diam., bears S.  $72\frac{1}{2}^\circ$  W., 71 lks. dist., with scribe marks S33 RE4079 BT visible on unhealed double blaze.

A fir, 5 ins. diam., bears N.  $9^\circ$  W., 34 lks. dist., with scribe marks S28 RE4079 BT visible on unhealed double blaze.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked

T 25 S R 2 W  
 S 28 | S 27  
 S 33 | S 34  
 1962

Deposit the original corner stone alongside the iron post.

The  $\frac{1}{4}$  sec. cor. of secs. 27 and 34, monumented with a basalt stone, 14 x 10 x 8 ins., firmly set 6 ins. in the ground, marked  $\frac{1}{4}$  on the N. face, from which the original bearing trees:

A cedar, 9 ins. diam., bears N.  $56\frac{1}{2}^\circ$  W., 16 lks. dist., with a healed blaze. (Record bearing, N.  $54^\circ$  W.)

A down hemlock, 12 ins. diam., bears S.  $78^\circ$  E., 6 lks. dist., with no marks remaining on decayed blaze. (Record bearing and distance, S.  $21^\circ$  E., 8 lks.) This tree has slid out of position with no remaining evidence of the stump hole.

and bearing trees marked by G. Robert Lecklider in 1960

A down fir, 15 ins. diam., bears N.  $46^\circ$  W.,  $46\frac{1}{2}$  lks. dist., with scribe marks  $\frac{1}{4}$  S27 RE4079 BT visible on unhealed double blaze.

A cedar, 18 ins. diam., bears West, 17 lks. dist., with scribe marks S34 RE4079 BT visible on unhealed double blaze.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 25 ins. in the ground, with brass cap marked

$\frac{1}{4}$  S 27  
 S 34  
 T 25 S R 2 W  
 1962

No suitable bearing tree available in sec. 34.

Deposit the original corner stone alongside the iron post.