

Dependent Resurvey, West Boundary, T. 23 S., R. 6 W.

CHAINS	Land, mountainous, with steep, bare slopes. Soil, light mantle of sandy loam, exposed sandstone. Timber, fir, hemlock, and cedar; undergrowth, salal, poison oak, vine maple, and fern.
	N. 1° 35' W., bet. secs. 25 and 30. Ascend 54 ft. over SW. slope.
8.02	Spur, slopes SW.; edge of logged area, bears E. and W.; desc. 5 ft. over NW. slope.
9.77	Creek, 3 lks. wide, course S. 75° W.; asc. 85 ft. over SE. slope, changing to W. slope.
12.96	Road, unimproved, bears N. 20° W. and S. 20° E.
14.19	Road, unimproved, bears N. 37° E. and S. 37° W.; also, top of ascent, slopes W.; desc. 17 ft. along W. slope.
18.44	Creek, 2 lks. wide, course SW.; asc. 82 ft. over SE. slope, changing to S. slope.
35.56	Spur, slopes W.; desc. 108 ft. over N. slope, changing to NW. slope.
39.47	Creek, 2 lks. wide, course N. 70° W.; asc. 2 ft. over SW. slope.
39.63	The $\frac{1}{4}$ sec. cor. of secs. 25 and 30, determined at record bearing and distance from the remaining original bear- ing tree: A fir, 62 ins. diam., bears S. 55° W., 85 lks. dist., with fragmentary scribe marks visible on double bark blaze. From this point, the $\frac{1}{4}$ sec. cor. of secs. 25 and 30, erroneously reestablished by Eggen, in 1957, bears S. 42° 42' E., 0.916 chs. dist., set, marked and witnessed as described in the official record. I remove the iron post, destroy the marks on the bearing trees, and at the original corner point Reset the iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 20 ins. in the ground, to bedrock, and in a mound of stone, 2 $\frac{1}{2}$ ft. base, to top, with brass cap marked T 23 S $\frac{1}{4}$ R 7 W R 6 W S 25 S 30 1957 from which new bearing trees A fir, 10 ins. diam., bears N. 47° E., 12 $\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S30 BT. A fir, 25 ins. diam., bears S. 82° W., 43 lks. dist., mkd. $\frac{1}{4}$ S25 BT. N. 0° 41' E., beginning new measurement. Ascend 30 ft. along broken W. slope.
5.43	Road, unimproved, 15 lks. wide, bears NW. and SE.