

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Subdivisional Lines, T. 23, S., R. 6 W.

CHAINS	
	Descend 130 ft. over SW. slope.
15.91	Spur, slopes SW.; desc. 265 ft. over SW. slope.
22.96	Road, graded, 25 lks. wide, bears N. 10° W. and S. 10° E.
28.66	Bear Creek, 10 lks. wide, course S. 15° E.; asc. 770 ft. over E. slope, changing to SE. slope.
42.46	Spur, slopes N. 60° E.; asc. 125 ft. over NE. slope.
47.67	Point for the $\frac{1}{4}$ sec. cor. of secs. 30 and 31, at proportionate distance; there is no remaining evidence of the original corner.
	From this point, the $\frac{1}{4}$ sec. cor. of secs. 30 and 31, erroneously reestablished by Eggen, in 1957, bears S. 39° 25' W., 0.36 chs. dist., set, marked and witnessed as described in the official record. I remove the iron post, destroy the marks on the bearing trees, and at the corner point
	Reset the iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap marked
	T 23 S R 6 W $\frac{1}{4}$ S 30 S 31 1957
	from which new bearing trees
	A fir, 8 ins. diam., bears N. 1° W., 47 lks. dist., mkd. $\frac{1}{4}$ S30 BT.
	A fir, 25 ins. diam., bears S. 7° W., 58 lks. dist., mkd. $\frac{1}{4}$ S31 BT.
	Ascend 74 ft. over NE. slope.
51.06	Ridge, bears N. 15° W. and S. 15° E.; desc. 753 ft. over SW. slope, changing to NW. slope.
53.22	Road, unimproved, 20 lks. wide; bears N. 10° W. and S. 10° E.
78.47	Road, unimproved, 20 lks. wide, bears N. 25° E. and S. 25° W.
82.68	Road, unimproved, 20 lks. wide, bears NE. and SW.
87.50	Road, unimproved, 20 lks. wide, bears N. 20° W. and S. 20° E.
93.40	The cor. of secs. 25, 30, 31, and 36, on the W. bdy. of the Tp.
	Land, mountainous. Soil, sandy loam. Timber, fir, maple, and cedar; undergrowth, vine maple, poison oak, salal.
	From the cor. of secs. 29, 30, 31, and 32. N. 10° 54' W., bet. secs. 29 and 30. Ascend 113 ft. along W. slope.