

Corrective Dependent Resurvey,
Line Between Sections 15 and 16, T. 31 S., R. 8 W.

CHAINS

I remove the iron post, destroy the marks on the bearing trees, and at the original corner point

Reset the iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass capmarked

$\frac{1}{4}$
 S 16 | S 15
 T 31 S R 8 W
 1961

from which new bearing trees

A cedar, 8 ins. diam., bears N. 60° E., 54 lks. dist., marked $\frac{1}{4}$ S15 BT.

A fir, 20 ins. diam., bears N. 24° W., 21 lks. dist., marked $\frac{1}{4}$ S16 BT.

N. 0° 10' W., beginning new measurement.

Descend 305 ft. over NE. slope.

8.60 Creek, 5 lks. wide, course N. 70° E.; asc. 350 ft. over broken SW. slope.

32.50 Dry bed of creek, 3 lks. wide, course S. 45° E.; asc. 270 ft. over SW. slope, changing to S. slope.

39.19 The cor. of secs. 9, 10, 15, and 16, monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap marked and witnessed as described in the official record of the 1961-64 dependent resurvey.

Land, mountainous.

Soil, rocky clay.

Timber, fir, hemlock, cedar, pine, yew, live oak, madrone, maple, chinquapin; undergrowth, live oak, hazel, salal, huckleberry, Oregon grape, poison oak, vine maple, ferns and vines.

GENERAL DESCRIPTION

The general description of this area is as described in the official record of the 1961-64 dependent resurvey.