

1460 County Surveyor's Record, Douglas County, Oregon

T. 21 S., R. 10 W., Willamette Meridian, Oregon

CHAINS

The following field notes describe the rehabilitation of an original corner point, T. 21 S., R. 10 W., Willamette Meridian, Oregon, as provided for in the General Special Instructions, Group No. 350, Oregon, dated May 3, 1957, "Investigation of Collateral or Physical Evidence of Corner Positions and Accessories Followed by Remonumentation of Corner Points, with New Accessories when Needed".

The rehabilitation was made at the request of the Coos Bay District Manager, for the administrative purposes of the Bureau of Land Management.

Rehabilitation of an Original Corner Point,
T. 21 S., R. 10 W., Willamette Meridian, Oregon

(Rehabilitation of a corner established by Menshch,
Collier, Rodolf, Strickler, and Sorrels in 1919)

The $\frac{1}{4}$ sec. cor. of secs. 1 and 12, monumented with an iron post, 1 in. diam., firmly set protruding 10 ins. above the ground, with brass cap marked

$$\frac{1}{4} \begin{array}{c} S 1 \\ S 12 \\ 1919 \end{array}$$

from which the original bearing trees

A stump hole, bears N. 11° E., 39 lks. dist., with the uprooted fir, 32 ins. diam., lying 50 lks. west, with illegible scribe marks visible on rotted blaze.

A cedar, 19 ins. diam., bears S. 80° W., 30 lks. dist., with illegible scribe marks in negative visible on overgrowth of rotted blaze.

and new bearing trees

A fir, 70 ins. diam., bears N. 63° E., 61 lks. dist., mkd. $\frac{1}{4}$ S1 BT.

A fir, 52 ins. diam., bears S. 41° E., 114 lks. dist., mkd. $\frac{1}{4}$ S12 BT.