

Corrective Dependent Resurvey of a Portion of
the Subdivisional Lines,
T. 27 S., R. 2 W., Willamette Meridian, Oregon

CHAINS

T 27 S R 2 W

 $\frac{1}{4}$

S 9 | S 10

1978 RLS 1005

from which the remains of the original bearing trees

A white fir stump, 22 ins. diam., bears S. $73\frac{3}{4}^{\circ}$ W.,
22 lks. dist., no marks visible on decayed
blaze.

and the remains of bearing trees mkd. by Corbin

A root hole, bears S. $54\frac{1}{4}^{\circ}$ E., 74 lks. dist., with
a down fir alongside, 20 ins. diam., with scribe
marks $\frac{1}{4}$ S10 BT visible on open blaze.

A cedar snag, 10 ins. diam., bears N. 40° W., 70
lks. dist., with scribe marks $\frac{1}{4}$ S9 BT visible
on open blaze.

and bearing trees mkd. by Tracy

A fir, 12 ins. diam., bears N. 38° E., $63\frac{1}{2}$ lks.
dist., with healed blaze.

A cedar, 18 ins. diam., bears N. 78° W., 27 lks.
dist., with healed blaze.

The corner monument established by Corbin, in 1957, was
destroyed by subsequent logging.

N. $0^{\circ} 21'$ W., bet. secs. 9 and 10.

Descend 65 ft. over NW. slope, through heavy timber and
dense undergrowth.

4.10 Creek, 4 lks. wide, course W.; desc. 2 ft. over NW.
slope.

6.60 Creek, 2 lks. wide, course W.; desc. 230 ft. over NW.
slope.

34.20 Little River, 40 lks. wide, course S. 70° W.; asc. 30
ft. over SW. slope.

35.35 Paved road, 30 lks. wide, bears N. 70° E. and S. 70° W.

40.63 Intersect the S. bdy. of sec. 3, and point for the
closing cor. of secs. 9 and 10.

From this point, the closing cor. of secs. 9 and 10,
erroneously positioned by Corbin, in 1957, bears
N. $0^{\circ} 09'$ W., 0.180 chs. dist., monumented with an iron
post, 28 ins. long, $2\frac{1}{2}$ ins. diam., firmly set 26 ins.
in the ground, mkd. and witnessed as described in the
official record.

I remove the iron post, and at the corner point

Reset the iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 18 ins.
in the ground, with brass cap mkd.

T 27 S R 2 W

S 3

S 9 | S 10

C C

1978

1957