

# County Surveyor's Record, Douglas County, Oregon

16735

Remonumentation of Certain Original Corner Points,  
T. 20 S., R. 8 W., Willamette Meridian, Oregon

**CHAINS**

S. 54° W., 19 lks. dist., no marks  
remaining on burned blaze. Rescribed T20S  
R8W S21 BT on new blaze.

and the remains of bearing trees marked in 1950

A sawed and burned cedar stump, 55 ins. diam.,  
bears N. 30° W., 61 lks. dist., no marks  
remaining on burned blaze. Rescribed T20S  
R8W S16 BT on new blaze.

and a new bearing tree

A sawed and burned cedar stump, 46 ins. diam.,  
bears N. 76° E., 12-1/2 lks. dist., mkd. T20S  
R8W S15 BT.

Set a 6 ft. steel fence post alongside the iron  
post.

(Rehabilitating a corner reestablished  
by Thomas A. Tillman in 1950)

The 1/4 sec. cor. of secs. 15 and 22, monumented with an  
iron post, 1 in. diam., firmly set, projecting 12 ins.  
above ground, with brass cap mkd.

$$\frac{1}{4} \begin{array}{l} S \ 15 \\ S \ 22 \end{array}$$

1950

from which the remains of the bearing trees marked in  
1950

A burned hemlock, 21 ins. diam., bears  
N. 40° E., 37 lks. dist., no marks remaining  
on burned blaze. Rescribed 1/4 S15 BT on new  
blaze.

A burned maple, 16 lks. diam., bears  
S 17° W., 19 lks. dist., no marks remaining  
on burned blaze. Rescribed 1/4 S22 BT on new  
blaze.

Set a 6 ft. steel fence post alongside the iron  
post.

(Rehabilitating corners reestablished by  
Thomas A. Tillman, Joseph S. Gawron, Hans W. Thielsen,  
and Raymond M. Bicknell, in 1954)

The 1/4 sec. cor. of secs. 15 and 16, monumented with an  
iron post, 1 in. diam., firmly set, projecting 10 ins.  
above ground, with brass cap mkd.

$$\frac{1}{4} \begin{array}{l} S \ 16 \ S \ 15 \end{array}$$

1954

from which bearing trees mkd. in 1954

A root hole, bears S. 8° E., 4-1/2 lks. dist.,  
with a down fir alongside, 50 ins. diam.,  
no marks remaining on burned blaze.