

County Surveyor's Record, Douglas County, Oregon

17531

Subdivision, Section 19,
T. 25 S., R. 4 W., Willamette Meridian, Oregon

CHAINS	
43.50	Creek, 2 lks. wide, course S. 65° W.; desc. over broken SW. slope.
55.15	Dirt road, 15 lks. wide, course N. 40° W. and S. 15° E.
73.70	Sutherlin Creek, 20 lks. wide, course N. 55° W.; asc. over NE. slope.
78.21	The 1/4 sec. cor. of secs. 19 and 24, on the W. bdy. of the Tp.
From the center E 1/16 sec. cor. of sec. 19.	
N. 1° 11' E., on the N. and S. center line of the NE 1/4 of sec. 19.	
Ascend over SW. slope, through heavy timber and dense undergrowth.	
7.40	Spur, slopes S. 65° W.; desc. over broken NW. slope.
20.20	The NE 1/16 sec. cor. of sec. 19, established and recorded by Victor M. McLind, Registered Land Surveyor No. 934, in 1971, and is accepted as the corner, monumented with an iron rod, 5/8 in. diam., firmly set, projecting 2 ins. above the ground, from which a bearing tree mkd. by McLind
A fir, 37 ins. diam., bears S. 62° E., 33 1/2 lks. dist., with healed double blaze.	
At the corner point	
Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.	
NE 1/16 S 19 1982	
from which a new bearing tree	
A fir, 17 ins. diam., bears N. 66° W., 60 1/2 lks. dist., mkd. NE 1/16 S19 BT.	
Reset the iron rod alongside the aluminum post.	
N. 1° 11' E., beginning new measurement.	
Descend over broken NW. slope.	
20.25	The E 1/16 sec. cor. of secs. 18 and 19.
From the N 1/16 sec. cor. of secs. 19 and 20	
S. 89° 33' W., on the E. and W. center line of the NE 1/4 of sec. 19.	
Ascend over NE. slope, through scattering timber and dense undergrowth.	
1.10	Spur, slopes N.; desc. over broken NW. slope.
19.74	The NE 1/16 sec. cor. of sec. 19.