

County Surveyor's Record, Douglas County, Oregon

17020

Corrective Dependent Resurvey,
Portion of the Subdivisional Lines,
T. 22 S., R. 9 W., Willamette Meridian, Oregon

CHAINS										
	From this point the $\frac{1}{4}$ sec. cor. of sec. 34 only, bears S. $89^{\circ} 28' W.$, 8.64 chs. dist., hereinbefore described.									
	From the cor. of secs. 21, 22, 27, and 28. N. $0^{\circ} 21' E.$, bet. secs. 21 and 22. Descend over NE. slope, through heavy timber and dense undergrowth.									
7.90	Creek, 4 lks. wide, course N.; thence along meandering creek bed.									
18.15	Leave creek, 4 lks. wide, course N. $20^{\circ} E.$; asc. over SE. slope.									
20.14	Point for the S $\frac{1}{16}$ sec. cor. of secs. 21 and 22. From this point the S $\frac{1}{16}$ sec. cor. of secs. 21 and 22, erroneously established by Wofford, Rogers, and Chatters, in 1973-79, bears S. $18^{\circ} 08' W.$, 0.0440 chs. dist., monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd. and witnessed as described in the official record. Remove the iron post, destroy the marks on the bearing trees, and at the true corner point Reset the iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> <table style="margin: auto; border-collapse: collapse;"> <tr> <td></td> <td style="text-align: center;">S $\frac{1}{16}$</td> <td></td> </tr> <tr> <td style="text-align: center;">S 21</td> <td style="text-align: center;"> </td> <td style="text-align: center;">S 22</td> </tr> <tr> <td></td> <td style="text-align: center;">1983</td> <td></td> </tr> </table> </div> from which A fir, 35 ins. diam., bears S. $40^{\circ} E.$, 22 lks. dist., mkd. S $\frac{1}{16}$ S21 BT. A fir, 27 ins. diam., bears S. $14^{\circ} W.$, 83 lks. dist., mkd. S $\frac{1}{16}$ S21 BT.		S $\frac{1}{16}$		S 21		S 22		1983	
	S $\frac{1}{16}$									
S 21		S 22								
	1983									
	Continue ascent over SE. slope.									
34.20	Spur, slopes N. $30^{\circ} E.$; desc. over NW. slope.									
40.28	The $\frac{1}{4}$ sec. cor. of secs. 21 and 22, monumented with the original sandstone, 16 x 12 x 8 ins., firmly set, 10 ins. in the ground, mkd. $\frac{1}{4}$ on W. face, alongside of which is an iron pipe, set by person(s) unknown, 1 in. diam., firmly set, projecting 2 ins. above ground. From this point the $\frac{1}{4}$ sec. cor. of secs. 21 and 22, erroneously reestablished by Wofford, Rogers, and Chatters, in 1973-79 bears S. $20^{\circ} 27' W.$, 1.007 chs. dist., monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd. and witnessed as described in the official record.									