

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 19 S., R. 10 W., Willamette Meridian, Oregon

18775

**CHAINS**

of the iron post is lying alongside, with brass cap mkd.

T19S	
R11W	R10W
S13	S 18
S 24	S 19
1918	

from which the remains of the original bearing trees

A root hole, bears N. 32° E., 26 lks. dist., lying alongside is a fir snag, 24 ins. diam., no marks visible.

A maple, 17 ins. diam., bears S. 64½° W., 14 lks. dist. with healed blaze. (Record, S. 74° W., 13 lks.)

A fir, 52 ins. diam., bears N. 88° W., 14 lks. dist. with healed blaze. (Record, N. 75° W.)

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd:

T19S	
R11W	R10W
S 13	S 18
S 24	S 19
1989	

from which new bearing trees

A fir, 53 ins. diam., bears N. 2° E., 114 lks. dist., mkd. T19S R10W S18 BT.

A fir, 7 ins. diam., bears S. 69½° E., 54 lks. dist., mkd. T19S R10W S19 BT.

Deposit the iron post inside and alongside the stainless steel post.

Corner is located on a S. slope in timber

This control line was fully retraced and careful search was made for evidence of intervening corners, none of which were recovered.

From the cor. of secs. 13 and 24, on the E. bdy. of the Tp.

S. 89° 56' 30" W., bet. secs. 13 and 24.

Ascend SE. slope, through logged area.

- 0.90 Spur, slopes SE.; desc. SW slope.
- 1.70 Dry creek bed, 2 lks. wide, course S. 80° E.; asc. E. slope.
- 3.30 Rock road, 15 lks. wide, bears N. 10° E. and S.
- 5.50 Spur, slopes S. 20° E.; desc. broken SW. slope.
- 19.335 Point for the E 1/16 sec. cor. of secs. 13 and 24.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.

E 1/16	S 13
	S 24
1989	

from which

A fir, 7 ins. diam., bears N. 55½° E., 14½ lks. dist., mkd. E 1/16 S13 BT.