

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

FIELD NOTES

OF THE

REHABILITATION OF THE 1/4 SECTION CORNER

OF SECTIONS 14 AND 15,

**TOWNSHIP 31 SOUTH, RANGE 5 WEST,**

OF THE WILLAMETTE MERIDIAN,

IN THE STATE OF OREGON.

**EXECUTED BY**

***A. Bert Skeesick, Cadastral Surveyor***

***Robert H. Browning, Surveying Technician***

Under Special Instructions dated July 13, 1979, approved July 17, 1979,  
and Supplemental Special Instructions dated May 20, 1985, approved  
May 24, 1985, which provided for the rehabilitation included  
under Group No. 1000, and assignment instructions dated May 11, 2000.

***Commenced September 25, 2000***

***Completed September 25, 2000***

**T. 31 S., R. 5 W., Willamette Meridian, Oregon**

FEET	<p>The following field notes describe the rehabilitation of the 1/4 section corner of sections 14 and 15, township 31 south, range 5 west, Willamette Meridian, Oregon, as provided for in the Special Instructions dated July 13, 1979, and Supplemental Special Instructions dated May 20, 1985, under Group No. 1000, Oregon, "Rehabilitation of Corner Points, Without Remonumentation, When Suitable Monument Exists."</p> <p>The rehabilitation of the 1/4 sec. cor. of secs. 14 and 15 was for administrative purposes of the Bureau of Land Management.</p> <p>The new bearing tree has a 2½ x ¼ inch magnetic nail (MAG-NAIL) driven at the base on the right side-center.</p> <p>The mean magnetic declination as taken from U.S. Geological Survey quadrangle map "CANYONVILLE, OREG.", Provisional Edition 1986, is 18° 30' East.</p>
	<p align="center"><b>Rehabilitation of the 1/4 Section Corner of Sections 14 and 15, T. 31 S., R. 5 W., Willamette Meridian, Oregon</b></p> <hr/> <p align="center">(Rehabilitating a corner remonumented by Daniel L. Berry and Charles E. Akin, Jr., Cadastral Surveyors, in 1972)</p> <hr/> <p>The ¼ sec. cor. of secs. 14 and 15, monumented with an iron post, 2½ ins. diam., firmly set, projecting 15 ins. above ground (with the original stone, 3 x 7 x 14 ins., mkd. ¼, and iron pipe, 1½ ins. diam., buried alongside), with brass cap mkd.</p> <div style="text-align: center;"> <p>T 31 S R 5 W</p> <p>S 15   S 14</p> <p>1972</p> </div> <p>from which the remains of a bearing tree</p> <p>A burnt, decayed stump, size indeterminate, bears S. 45° E., 7.9 ft. dist., with no scribe marks visible.</p> <p>and the remains of a bearing tree mkd. by King,</p> <p>A burnt fir snag, 23 ins. diam., bears N. 41° W., 23.1 ft. dist., with a healed blaze.</p> <p>and the remains of a bearing tree mkd. by Powell, Jones and Brady</p> <p>A burnt fir snag, 13 ins. diam., bears S. 59° E., 11.2 ft. dist., with a healed blaze.</p>

Rehabilitation of the 1/4 Section Corner of Sections 14 and 15,  
T. 31 S., R. 5 W., Willamette Meridian, Oregon

FEET	
	<p>from which a new bearing tree and a reference monument</p> <p>A fir, 16 ins. diam., bears N. 62° E., 35.0 ft. dist., mkd. ¼ S14 BT.</p> <p>A stainless steel post, 28 ins. long, 2½ ins. diam., set 25 ins. in the ground for a reference monument, bears N. 55° W., 16.0 ft. dist., with brass cap mkd. RM T31S R5W ¼ S15 16.0 FT TO COR 2000 and an arrow pointing to the corner.</p> <p>Reset the iron post, 21 ins. in the ground, over the iron pipe, 21 ins. in the ground, buried stone inverted alongside the iron post.</p> <hr/>