

Ben B Drwing D.C.S.
(Rev. #16) Jan 8, 1936
Wit N.E. Richardson
(Rev. #17) J. F. Lamphear

1/4 Section Corner between sections 10 & 15. Location identified from an O.B.T. a white Oak which bears N16°0E 54 ch. This tree is down & rotting, the blaze marks were plain but the scribe marks had rotted off. The O.B.T. 511 1/4° W 116 lks had been completely destroyed by fire, the stump hole where the tree stood checked for bearing & distance.

Drove a 1/2" x 12" iron bolt for the corner & set a 6" white post alongside 24" above ground and scribed 1/4 S on the E face, S 15 CS on the S face, & S 10 on the N face.

Marked New Bearing Trees { a W. Oak 16" S 43° W 83.4 feet
{ an Oak 8" N 51° W 1390 "

Blazed & Scribed 1/4 S S 10 CS, B.T. on 8" Oak.
" " " " S 15 " " " 16" " "

1/4 Section corner between section 15 & 22. Location identified from property corner & line fence. This fence corner has been used for a great many years as the true corner there never been questioned. Its location fits the local topography as recorded in the Orig. govt field notes. All local traces of the original corner have disappeared. Drove 3/4" x 24" piece of shafting with a gear attached for the corner at fence corner described in the previous paragraph. There are no trees near available for bearing so none were set. A 1/2" x 27" bolt for property corner bears N 0° - 11 E 1320 feet along the line through center of section 15. A 3/4" x 38" iron pin set for a property corner is S 89° 36 W 1320 feet