

Douglas County Surveyor's Record of
Government Corners Renewed

T. 20 S. T. S. R. 9 W. R. W. W. M.

5
 $\frac{1}{4}$ Corner Section 18, only, T20-8W.
 Found - GLO Brass Cap mkd. 1954.
 26" Fir N. $41\frac{1}{4}^\circ$ E. 31 lks. scribed $\frac{1}{4}$ SL8 BT
 20" Hemlock S. $30\frac{1}{4}^\circ$ E. 5 lks. This tree is blown down.
 Set - Set Brass Cap for Witness Corner marked:
 W. C. 40' West to $\frac{1}{4}$ /SL8 T20S R&W
 County Surveyor's Office, 1965
 New BT's: 12" Hemlock N. 72° W. 7.8 ft. scribed W.C. SL8 CS BT.
 12" Hemlock N. $40\frac{1}{2}^\circ$ E. 4.3 ft. scribed W.C. SL8 CS BT.

6
 $\frac{1}{4}$ Corner to Sections 16 and 17.
 Found - GLO Brass Cap Mkd: 1953.
 34" Fir N. $7\frac{1}{2}^\circ$ E. 14 lks. scribed $\frac{1}{4}$ SL6 BT. This tree
 has been cut. **RE-RENEWED SEE CORNER NO. 11**
 No trace of 5" Fir S. 50° W. 19 lks.
 New BT's: 6" Hemlock N. 82° E. 11.1 ft. scribed $\frac{1}{4}$ SL6 CS BT.
 8" Hemlock S. $23\frac{1}{2}^\circ$ E. 41.3 ft. scribed $\frac{1}{4}$ SL6 CS BT.
 Note - This corner is right on top of a cut bank on
 Johnson Ridge Road, right hand side of road going North.

MICROFILM TO HERE 10/67

7
 East $\frac{1}{4}$ Corner to Section 1, T20-10W.
 Found - 1" I.P. filled with cement at corner point with 1951
 Brass Cap broken off.
 Orig. 36", now 40" Fir, alive, S. 66° W. 16.5 ft., shows
 good scar. We do not open.
 6" Yew S. $86\frac{1}{2}^\circ$ W. 38.9 ft., alive, scribe visible on
 partially healed blaze. (1951 BT)
 Set - Brass Cap at Cor. Mkd: County Surveyor's R T 20 S R
 (Deposit old pipe Office 10 $\frac{1}{4}$ S 1 9
 alongside) 1968 W W
 Note - This corner lies on very steep N. slope approx. 50 ft.
 south of small creek, course N. W.

April 11, 1968

8
 Closing Corner Sections 5 and 4.
 Found - 1921 G.L.O. Brass Cap with badly rusted pipe, buried under
 48" Cedar Log.
 14" Maple, now 20" shattered stump, S. 38° E. 17.8 ft., no
 scribe found on unhealed blaze.
 30"(?) Alder, now 24" Stump, S. 15° W. 40.3 ft., blaze
 decayed, no scribe.
 Set - Brass Cap at Cor. Mkd: County Surveyor's CC T 19 S
 (Deposit old corner Office S 5 S 4
 material alongside) 1968 T 20 S R 9 W
 New BT: 30" Maple N. 12° W. 67.6 ft. mkd. "CC S4 S5 CS BT.
 No other trees available.
 Note - This corner lies 20 ft. E. of small ravine, course N.E.
 and 200 ft. S. of Middle fork of Smith River.

7/19/68

9
 Section Corner to Sections 32 and 33., T19 - 9 W.
 Found - 1921 G.L.O. Brass Cap, in place & firmly set.
 Orig. 20", now 26" Fir sawed stump, N. 83° W. 22.4 ft., shows scar.
 No trace other BT, due to slide.
 There being no trees close, we set $\frac{5}{8}$ " I. Rod in front of BT. Stump
 on N. 83° W. bearing 20.9 ft.
 Set - $\frac{5}{8}$ " I.R. North 10.0 ft.
 6" Steel Fence post alongside Brass Cap.
 This corner lies on very steep northerly slope approx. 200' ft. from
 log landing in Section 5.

7/19/68

10
 Closing Corner Sections 6 and 7, T20-9W.
 Found - Concrete filled I.P., no brass cap, broken off.
 Orig. 30", now 34" Cedar, alive, N. 37° E. 34.3 ft., shows good scar.
 Rescribe "T20S R9W S6 CC CS BT".
 Orig. 40" Cedar, now 42" sawed stump, S. $82\frac{1}{2}^\circ$ E. 61.4 ft. scribe vis.
 No other Trees to S.E. No suitable trees close N.E. or W.
 Note - Corner Pipe was under logging debris which we removed.
 (continued next page)

John M. Powell
 Joe Brady
 Oct. 13, 1965
 C.S. File No. 53/66

John M. Powell
 Frank Jones & W. Penley
 G. S. File No. 53/66