

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Secs. 4 & 3, T21-8W. & Secs. 33 & 34, T20-8.
Found - Existing Brass Cap set by U. S. Cadastral Engineers and
2 Bearing Trees in Section 33.

18

Set - Three BT's., as follows:

- Bark Scribed 24" D. Fir Stump S.70°W. 28.1 ft.
- Bark Scribed 42" D.F. Stump S.47°E. 88.9 ft.
- Bark Scribed 22" D.F. Stump N.37°45'E. 50.0 ft.

Nov. 1968

SEPT. 68

Ronald E. Stuntzner
For Coos Head
Timber
C.S. File
No. 55/99

Sec. Corner, Sections 19 and 30 only.

19

Found - GLO Brass cap properly mkd., 1945
52" Fir stump, burnt, S.20°E., 89.1 ft. Shows part of face.
54" Fir stump, burnt, N.17½°E., 237.6 ft.

New BT's - 5" D. Fir, N.54°E., 7.3 ft. Scribed S19 CS BT.
5" D. Fir, S.59°E., 19.1 ft. Scribed S30 CS BT.

Note - This Corner lies in old clear cut very brushy. Also lies
on westerly slope.

5/11/73

MARCH 71

John M. Powell, Surveyors Office
G. Commons
May 11, 1973
C.S. File 56/25

Sec. corner, Sections 24 and 25 only, T21-9.

20

Found - GLO Brass Cap C.C. properly mkd, 1945
26" Fir stump, N.80°E., 63.4 ft. Open for Scribing B.T.
48" Fir stump, N.33°W., 143.9 ft.
1" Iron pipe along side of Brass cap.

New BT's - 6" D. Fir, N.31°W., 11.3 ft. Scribed S24 CS BT.
8" D. Fir, South, 29.9 ft. Scribed S25 CC CS BT.

Note - This corner lies in old clear cut very brushy. A lot of new
growth. It lies on westerly slope approx. 60 ft. westerly
of ridge top.

5/11/73

Renewed #48

1/4 Corner, Sections 30 and 29.

21

Found - 1960 Cadastral Brass cap in place with steel fence post
set alongside.

1945 - 48" Fir (stump) S.53½°W., 109.6 ft., in place, no
scribe found.

1960 - 56" Fir, (dead) N.72½°E., 335.9 ft. scribe visible on
unhealed blaze. "1/4 S29"

New BT's - 7" D. Fir, S.68°W., 39.9 ft. scribed "1/4 S30 CS BT."
8" D. Fir, N.80°E., 50.0 ft. scribed "1/4 S29 CS BT."

Note - This cor. lies on west edge of fire road in area of very
dense reprod. Road bears approx. N.60°E. and S.60°W.

V. R. Tracey, Surveyor's Office
J. Heritage
C.S. 56/34
July 5, 1973

WC to Sections 30, 29, 31, and 32.

22

Found - 1945 GLO brass cap properly mkd., in place, firmly set.
Old BT's are now burned stumps and badly decayed. No scribe
found on blazes due to burn.

New BT's - 9" D. Fir, S.22½°W., 31.0 ft. mkd. "WC T21S R8W S31 CS BT"
8" D. Fir, S.7°E., 22.9 ft. mkd. "WC T21S R8W S32 CS BT."
6" D. Fir, N.72°E., 14.0 ft. mkd. "WC S29 CS BT."
9" D. Fir, N.41°W., 29.2 ft. mkd. "WC T21S R8W S30 CS BT"

Note - This witness cor. lies 6.6 ft. N.0°25'E., of true cor. as
recorded in Govt. field notes.

Section Corner to Sections 33 and 35 only.

23

(on ~~34~~ Line of Sec. 3 T22S R8W)

Found: Remains of one BT marked in 1945, A fragmented, rotten Hemlock
stump bearing N.46°45'W., 57.4 ft., with scribing "W S33 BT" visible.
The brass cap set in 1945 and all other corner accessories have been
destroyed.

Due to extremely steep slopes, shallow soil and loose rock, it is im-
practical to set any type of permanent monument. We do however,
place a steel fencepost at the corner point.

We mark the following new BT's.

- An 8" Red Alder bears N 55°W., 34.7 ft. scribed "T21S R8W S33 CS BT"
on a double blaze.
- A 7" D. Fir bears N 51°E., 23.6 ft., scribed "T21S R8W S34 CS BT"
on double blaze.

Compass Declination: 20° East.

JAN 73

Gary L Langlitz
Clell E Goodwin
M. Lenora Ladig
A. Vic Cangie
8/7/75
C.S. 57/34

RECORDED
CORNER NO. #52