

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 9 W. R. W. W. M.

Sec. Corner to Secs. 5 & 6, T21-9W. and Secs. 31 & 32, T20-9W.  
Found - Unmarked Pipe Cap & also GLO Brass Cap mkd. in 1953.

34" Cedar, now stob, S.85 $\frac{1}{2}$ °W. 58.1 ft., scribe visible  
33" D.Fir, now stump, S.83°E. 77.2 ft., partial scribe visible,  
11", now 13" Maple, N.2°E. 103.0 ft., mostly grown over.

New BT's: 14" Maple W. 7° E. 22.3 ft. mkd: T20S R9W S32 CS BT.  
12" Maple N.46°W. 22.6 ft. mkd: T20S R9W S31 CS BT.  
15" D.Fir S.23°E. 23.8 ft. mkd: T21S R9W S 5 CS BT.  
16" Maple S.50°W. 21.7 ft. mkd: T21S R9W S 6 CS BT.

This corner is in E - W Fence Line.

9/29/69

Section Corner to Sections 1 and 12, T21 - 10W.  
Found - GLO Brass Cap marked in 1919.

22" D. Fir, now snag, S.33°W. 42.9 ft., shows scar.  
36", now 36" D.Fir, N.10°W. 28.4 ft., shows good scar  
20" D.Fir S.20°W. 67.3 ft., pitched over scribing visible.

New BT: 17" D.Fir N.59 $\frac{1}{2}$ °E. 40.2 ft. scribed T21S R9W S 6 CS BT.

Note - I renew this corner because of new road to be built. S.W. BT  
is on top of ridge and will probably be taken out.  
Road St. P. Line 72 - 30.

9/30/69

South  $\frac{1}{4}$  Corner Section 34 only, T20-9W

Found - GLO Brass Cap, date 1953, properly marked.

20" D. Fir, now stump, N.49 $\frac{1}{2}$ °E. 33.0 ft. Shows good scar.  
Northwest BT buried by logging show.

Set - Steel fence post along side Brass Cap.

New BT's: 14" Hemlock S.85°W. 69.7 ft. scribed C.S. BT  
30" Cedar S.44 $\frac{1}{2}$ °E. 77.4 ft. scribed C.S. BT.

To the north of this corner is clear cut.

5/27/71

$\frac{1}{4}$  Corner to Sections 3 and 2.

Found - HLM brass Cap, date 1963, properly marked, buried under large  
log.

18" Hemlock down N39°W. 15.5 ft. scribed visible "4 S3".  
22" Hemlock dead N.87°E. 19.8 ft.. Shows scar.

New BT's: 12" Maple S79°E. 39.0 ft. scribed  $\frac{1}{2}$ S2 CS BT.  
9" Hemlock S69°W. 31.5 ft. scribed  $\frac{1}{2}$ S3 CS BT.

5/27/71

Section Corner to Sections 30, 29, 31, 32.

Found - 1967 HLM Brass Cap properly marked.

42" D. Fir, now 50", N.17°E., 58.1 ft. Shows scar.  
6" Cedar, now 7", S.84°W., 42.9 ft. T21S R9W S31 BT.  
32" D. Fir, now 40", N.19°W., 15.8 ft. Shows old scar.

New BT's: 12" Cedar, S.14 $\frac{1}{2}$ °E., 51.4 ft. Scribed T21S R9W S32 CS BT.  
24" Cedar, N39°W., 26.4 ft. Scribed T21s R9W., S30 CS BT.

Note: Area to the south has been logged.

9/30/71

$\frac{1}{4}$  Corner to Sections 31 & 32.

Found - 36" D. Fir, now stob, N.48°E., 24.4 ft. opened earlier for  
scribe "BT".

40" D. Fir, now stump hole, N.44°E., 85.1 ft.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1971  
T 21 S  
 $\frac{1}{4}$  S31 | S32  
R 9 W

New BT's: 14" D. Fir, N.10°W., 13.5 ft. scribed  $\frac{1}{2}$ S31 CS BT  
7" D. Fir, S.43°E., 18.5 ft. scribed  $\frac{1}{2}$ S32 CS BT.

Note: Call of 1 chain to top spur hits good. Road approx. 50 ft.  
west of road.

9/28/71

John M. Powell  
Frank Jones & W. Penley  
Sept. 1969 C. S. File No. 53/66

MARCH 71

John M. Powell  
J. Heritage  
May 1971  
C.S. File 53/66

John M. Powell  
W. Penley & J. Heritage  
September, 1971  
C.S. File 53/66

Fd.  
by Robert  
Less  
Dues  
90-30

RE-RENEWED SEE CORNER NO. #60

RE-RENEWED SEE CORNER NO. #37

Fd  
12/26/90  
ROBERTS  
M 109-42