

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 11 W. R.W.W.M.

Milo E.  
Godfrey &  
Crew  
Sept. 1964  
C. S. File  
No. 53/66

$\frac{1}{2}$  Corner to Sec. 2, T21-11W. & Sec. 35, T20-11W.  
Found -  $\frac{3}{4}$ " Iron Pipe. See Ren. #2, T20-11W. #267200 #139  
52" Red Cedar S.10°W. 12.0 ft., prev. opened thru rotten wood  
on south side, good reverse scribing vis. on overgrowth of old fee  
Fir Stump S.82°W. 11.2 ft., cut open below markings.  
Eppstein's other BT. destroyed by road construction.  
New BT's: 23" Red Cedar N.58°E. 34.4 ft. Mkd:  $\frac{1}{2}$  S35 CS BT.  
52" Red Cedar S.10°W. 12.0 ft. Mkd:  $\frac{1}{2}$  S2 CS BT. (Orig. BT.)  
Corner is on top edge of cut bank on E. side of Smith River Road.

31

Milo E.  
Godfrey &  
Crew  
Nov. 1964  
C. S. File  
No. 53/66

Sec. Cor. to Secs. 18 & 19, T21-11W. & Secs. 13 & 24, T21-12W.  
Found - 2" Iron Pipe mentioned by F. Cain (See Ren. #3).  
Pipe extends approx. 12" above ground.  
No trace of any Original Bearing Trees.  
New BT's: 16" D.Fir S. 8°W. 8.4 ft. Mkd: T21S R12W S24 CS BT. 60  
14" D.Fir S.60°E. 24.7 ft. Mkd: T21S R11W S19 CS BT.  
13" D.Fir N.77°E. 27.2 ft. Mkd: T21S R11W S18 CS BT.  
No suitable trees near in Sec. 13.  
DID NOT SET BRASS CAP - Corner is approx. 500 ft. West of Smith River Road.  
Nov. 25, 1964

32

Bruce R. Rogers  
Mike Stone  
June 1965  
C. S. File No. 53/66

Section Corner to Sections 7 - 8 - 17 - 18. (Corner Found)  
Found - Orig. 36" Fir, now 44" N.25°W. 27.1 ft., chopped out to  
good face, shows scribing (straight lines).  
Orig. 30" Fir, now 40" N.45°E. 29.7 ft., shows good bear,  
did not open. Fd. July, 1982 #158  
Orig. 16" Fir, new rotten stump. SEE M 93-10  
1 $\frac{1}{2}$ " Iron Pipe at Corner with Cap Mkd: 

S 7	S 8
S 18	S 17

33

James W. Byron, Co. Surv.  
M. Darby-M. Stone-J. Connell  
July 1965  
C. S. File No. 54/15

Section Corner to Sections 8 - 9 - 16 - 17. #107 34  
Found - 1 $\frac{1}{2}$ " I. Pipe with Cap 4 ft. above ground Mkd: 

8	9
17	16

 (Ren #5)  
36" Fir S.11 $\frac{1}{2}$ °W. 79.6 ft. (Ren #5)  
Other Bearing Trees gone.  
New BT: 10" Alder, forked, bears N.70°W. 5.5 ft. scribed S 8 CS BT.

$\frac{1}{2}$  Corner to Sections 8 and 17. 35  
Set by Proportionate Measurement.  
Set - Brass Cap at Cor. Mkd:  $\frac{1}{2}$  S 

8
17

 T21S R11 W. Fd. July, 1982 SEE M 93-10  
County Surveyor's Office, 1965  
New BT's: 12" Hemlock bears N.35°E. 7.0 ft. Mkd:  $\frac{1}{2}$  S8 CS BT.  
7" Hemlock S.6°W. 16.3 ft. Mkd:  $\frac{1}{2}$  S17 CS BT  
Note - Corner falls 40 ft. north of top of slope of E - W Ridge.

Wit. Corner for W. 1/16 to Sections 8 and 17. 36  
Set - Brass Cap Witness Corner Mkd: County Surveyor's Office, 1965  
Wit. Cor. W 1/16 S 8 T21S R11W  
New BT: 58" Cedar bears S.10°E. 10.5 ft. scribed  $\frac{1}{2}$  S17  
W 1/16 S 8 W.C. CS BT.

Closing Township Corner. 37  
Fd. - Orig. 40"?, now 22" Fir Stump, N. 6° E. 21.1 ft., shows "SR11WS" on  
opened blaze, prob. 14" when mkd. Ring count 60+ years.  
Orig. 40", now 48" Fir, tipped out stump laying face down, #241  
N. 43° W. 20.5 ft. No trace of SE BT.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 T 20 S CC S 31 R11W  
T 21 S R12W S 6  
New BT: 30" D. Fir Stump S. 20° E. 6.3 ft. mkd. T21S R11W S 6 CC CS BT.  
No other stumps or trees close.  
Note - This corner lies on very steep, NE slope, approx. 195 ft. S. of  
Twp. Cor. of T.20 & 21S., R.12W., See corner below.  
Brass Cap is set on E. side and under 30" Log.

Vernon "Ray"  
Tracy &  
Crew  
3/30/67  
C.S. File  
No.  
54/1

Fd. #102  
See M 93-10  
for new  
BT.