

Douglas County Surveyor's Record of
Government Corners Renewed

22

T. S.

4

R. W. W. M.

ROSE CHAPMAN CO. PUBLISHER, DES. 21881

50

$\frac{1}{4}$ Corner common to Sec. 33 - 22S-4W
Sec. 4 - 23S-4W
GLO Survey Record - Post, No trace. *SEE ALSO #3A*
12" Laurel S. 38°E. 10.6 ft. - 18" Laurel, down, rotted, &
hollow, but scribing visible.
8" Fir N. 18°W. 39.6 ft. - 28" Fir - Scribing Visible.
Found 1" Iron Rod for corner, good for dist. & bear. from GLO BT's.
Referenced by G. McChesney (Plates & "W" nails only) Decl. 20°
28" Fir N. 17°W. 38.2 ft. Orig. BT.
44" Fir S. 5°W. 45.6 ft.

RE-RENEWED SEE CORNER NO. #133

51

C $\frac{1}{4}$ Corner for Section 33.
County Survey Record 1915 *REN. #16*
Set Corner - 9" Oak N. 3 $\frac{1}{2}$ °E. 513.5 ft. - gone
24" Maple S. 65°E. 164.3 ft. - gone
14" Ash N. 15°W. 609.2 ft. - 20" Ash - 2 faces healed over.
7" Oak S. 23°35'W. 309.5 ft. - 24" Oak, scribing visible.
Drove a Weyerhaeuser Co. "W" nail into paved Co. Rd. by dist. from
N.W. & S.W. CS BT's.
Referenced by G. McChesney - Decl. 20°
1" Iron Rod N. 4°E. 34.0 ft. CR R/W P.O.T 110 + 50
1" Iron Rod S. 7 $\frac{1}{2}$ °E. 26.5 ft. " " "
10" Pwr. Pole N. 20°E. 36.5 ft. Plated & "W" nails only.

Weyerhaeuser Timber Co.
By Glen McChesney
Under Lester E. Calder
June 1960
C. S. File No. 51/87

RE-RENEWED SEE CORNER NO. #134

52

C $\frac{1}{4}$ Corner for center Sec. 34.
Found 1 $\frac{1}{2}$ " Iron Pipe and old 4" x 4" Oak Post scribed "CS" for corner.
According to the Woodard Survey Notes, C. Randall placed
the above 1 $\frac{1}{2}$ " iron pipe alongside the scribed 4" x 4" Oak Post
which he found in existence at the time of his survey. Randall's
survey notes also indicate that this corner is 21.2 feet to far
to the East.
In view of the fact that W. Haines used this corner to
establish the CE 1/16 corner in May, 1960, the point was
referenced as follows:
Referenced by William Wilt (Plates & "W" nails only).
Decl. 20° 14" Fir S. 66°E. 14.4 ft.
12" Fir S. 18°W. 16.6 ft.

Weyerhaeuser Timber
By Lyle E. Boustead
January 1961
C. S. File No. 51/87

53

$\frac{1}{4}$ Section Corner to Sections 20 and 21. *SEE ALSO COR. #72*
Found - Old rotten Fir Snag, bark gone on N.E. Side, S. 50°W. 15.2 ft.
Old Stump Hole with pieces of rotten Maple N. 62°E. 22.4 ft.,
A maple tree is now growing in S.W. side of hole, no scribing.
Old 1 $\frac{1}{2}$ " Pipe with Cedar Tree to N.E. showing scribing in scar
opened several years ago. (now nearly healed over again) bears
N. 33°E. 2.9 ft.
Corner of old wooden fence, nearly all down, bears N. W. 5.5 feet.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1961 T22S R4W
 $\frac{1}{4}$ S7221
The Cedar mentioned above, 17", bears N. 23°E. 11.0 ft., scribing
visible "1/4 SRS".
New BT's: 8" R. Cedar N. 57°W. 21.4 ft. Mkd: $\frac{1}{4}$ S20 CS BT.
Creek crossing North of corner checks call in gov't field notes.

Milo E.
Godfrey
Vernon Tracy
Clate Putnam
Dec. 21, 1961
C.S. File
No. 49/42

See That's
old Box 3
Pg 21

54

Section Cor. to Secs. 4 & 5, T22-4W. & Secs. 32 & 33, T21-4W.
Found - Stake badly decayed, Orig. BT., down & destroyed except the
Yew Tree and it was down, marks visible.
Set - New Post, Yew, 4 x 4 inches square 3 $\frac{1}{2}$ ' long from which:
6" Fir bears N. 7 $\frac{1}{2}$ °E. 23 lks.
6" Fir bears N. 37 $\frac{1}{2}$ °W. 21 lks.
5" Fir bears S. 32°E. 21 lks.
No tree near in S. W.

W. F. Briggs.
Wit: Pete Matchatte &
S. Tonalee
March 16, 1901
Vol. 2, Page 263

SEE CORNER NO. 93