

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

63

C. S. File 49/158
M 15 - 18

FDCK 9/86
IN 102-61
T. FLAT 680

$\frac{1}{4}$ Section Corner to Sec. 18, T22S.R5W. & Sec. 13, T22S. R6W.
Found - Orig. 18", now 42" B. Oak, previously opened, shows
good scribing $\frac{1}{4}$ ", N.16 $\frac{1}{2}$ °E. 237.6 ft.
Remains of large Oak that would check close for Orig. #157
N. W. BT.
Find Channel Iron 1" x 3" at Corner & under N.S. Fence.
New BT's: 7" Black Oak bears N. 8 $\frac{1}{2}$ °E. 19.8 ft. scribed $\frac{1}{4}$ " S18 CS BT.
15" " Oak bears N.18 $\frac{1}{2}$ °W.168.2 ft. scribed $\frac{1}{4}$ " S13 CS BT.

RE-RENEWED, SEE CORNER NO. #157

64

Section Corner, Secs. 4 & 5, T22S R5W, and Secs. 32 & 33, T21S R5W.
Found - 12", now 40" Fir N.42°E. 11.2 ft., shows good scr, I
do not open.
Remains of Rotted Stump, checks bearing & distance for
Original N.W. BT.
Fir Snag, previously opened, shows good scribing,
S.50 $\frac{1}{2}$ °W. 23.0 ft. (Cole)
Cole's N.69 $\frac{1}{2}$ °E. 58.0 ft. BT., previously opened.
I find 1" Iron pipe at Corner driven in, 1 $\frac{1}{2}$ " Iron Pipe set by Cole.
I do not set Brass Cap at Corner.
New BT's: 2" R. Fir bears N.51° W. 18.0 ft. scribed T21S R5W S32 CS BT.
6" R. Fir bears S.38 $\frac{1}{2}$ °W. 39.5 ft. scribed T22S R5W S 5 CS BT.
8" R. Fir bears S.20° E. 31.0 ft. scribed T22S R5W S 4 CS BT.

RE-RENEWED, SEE CORNER NO. #209

SEE REN. #
IN T. 21-5

FDCK - M121 - 21 - 11/10/94

65

$\frac{1}{4}$ Section Corner to Sec. 5, T22S R5W, and Sec. 32, T21S R5W.
Found - No Original BT's, but both of Theill's BT's: - REN. #1
20", now mostly rotted Chinquipin Stump, good scribing "BT",
Fd. S.11°E. 29.7 ft.
14", now 30" Fir Stump, checks bearing & distance for N.W. BT.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959
New BT's: 38" R. Fir bears N. 7°E. 19.4 ft. scribed $\frac{1}{4}$ " S32 CS BT.
13" R. Fir bears S.71 $\frac{1}{2}$ °E.70.3 ft. scribed $\frac{1}{4}$ " S 5 CS BT.
17" Laurel " S.54 $\frac{1}{2}$ °E. 44.2 ft. scribed $\frac{1}{4}$ " S 5 CS BT.

RE-RENEWED, SEE CORNER NO. #208

FD: B.C.
8/84
F. Williams
M 97-98

66

Section Corner to Sections 4, 5, 8 and 9.
Found - All Four of Eppstein's BT's: - REN. #53
20", now 24" R. Fir S.40°E. 8.4 ft., previously opened,
shows good scribing "S 2".
S.W. & N.W. BT's, now Stumps.
N. E. BT., now down, all check bearings & distances.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959
New BT's: 24" R. Fir bears S. 8°W. 26.3 ft. scribed S 8 T22S R5W CS BT.
6" W. Oak bears N. 4°W.102.6 ft. scribed S 5 T22S R5W CS BT.
11" R. Fir bears N.26°E. 49.8 ft. scribed S 4 T22S R5W CS BT.
Note: Corner is on large Sandstone, Top of Brass leans to West
but is on Corner.

RE-RENEWED, SEE CORNER NO. #112

67

South $\frac{1}{4}$ Corner to Section 36 only.
Found - Orig. 12" B. Oak, now down, N.30°E. 33.7 ft. I open &
find good scribing "B".
Orig. 24", now 40" B. Oak N.60°E. 2.6 ft., shows good
scars. I do not open.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960.
South $\frac{1}{4}$ Corner S36 T22S R5W.
New BT's: 17" R. Fir bears N.10°E. 17.5 ft. scribed S $\frac{1}{4}$ " S36 CS BT.
13" R. Fir bears N.33°W. 26.1 ft. scribed S $\frac{1}{4}$ " S36 CS BT.

RE-RENEWED, SEE CORNER NO. #173

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
August 19, 1959
C. S. File No. 49/59

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
January 15, 1960
C. S. File No. 49/42