

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T. S. R. 5 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

81

Sec. Cor. 1 & 12, T22-5W. & Secs. 6 & 7, T22-4W.  
Old Post, found. Placed new post 5" x 5" x 5'-0" and  
Iron Pin 1/8" x 16" Long.

Orig. BT: Fir 20" S.18°E. 68 lks. dist., Windfall, scribed **57 & 133**  
All other bearing trees destroyed.

New BT's: 14" Chinq. S.30°E. 14.5 ft. Mkd: T22S R4W S7 BT.  
42" Fir S.7°15'W. 40.1 ft. Mkd: T22S R5W S12 BT.  
38" Fir N.74°W. 57.9 ft. Mkd: T22S R5W S 1 BT.  
18" Cedar N.15°30'E. 46.0 ft. Mkd: T22S R4W S6 BT.

82

1/4 Corner to Sections 1 and 12.  
Orig. bearing trees destroyed.

Corner established by single proportion between Sec. Corners.

Scribed BT's: 22" Fir S.62°E. 43.8 ft. Mkd: S 1/2 R.P. BT. - RESEARCHED FOR MAY 1965

34" Fir N.33°W. 81.5 ft. Mkd: S 1/2 R.P. BT. NOT FOUND - C.S. 53/101

FOUND SEE NOTE ON SHANER'S 1972 SURVEY M 42-68

Section Corner to Sections 1 - 2 - 11 - 12.  
Original bearing trees destroyed.

Corner established by orig. blaze intersection and Found Rock.

New Post in pile of rocks from which scribed BT's:

24" Cedar S.37°E. 28.1 ft. Mkd: T22S R5W S12 R P BT  
13" Fir S.85°W. 24.9 ft. Mkd: T22S R5W S11 R P BT.  
54" Fir N.46°W. 49.10 ft. Mkd: T22S R5W S2 R P BT.  
30" Fir N.16°E. 19.4 ft. Mkd: T22S R5W S 1 R P BT.

SEE SHANER'S 1972 SURVEY M 42-68

Section Corner to Sections 10 - 11 - 14 - 15.  
Original BT's. destroyed.

Post & 1" x 5'-0" Iron Pipe - Fir 30" N.10°W. 2.5 ft. dist.  
mkd: T22S R5W S10 RP. BT.

Fir 30" S26°W. 41.9 ft. Mkd: T22S R5W S15 RP BT.  
Fir 32" S.31°E. 47.5 ft. Mkd: T22S R5W S14 RP BT.  
Fir 26" N.25°E. 25.0 ft. Mkd: T22S R5W S11 RP BT.

37

83

SEE SHANER'S 1972 SURVEY M 42-68

84

1/4 Corner between Sections 10 and 11.

New Post & 1" x 5'0" Pipe for Corner.

Original Bearing Trees: Fir 24" S.65°W. 32 lks. (scribed on bark) now 36".  
Fir 24", now 40" N.50°E. 34 lks. (scribe burned)

85

Section Corner to Sections 2 - 3 - 10 - 11.

New Post & Iron Pipe - 5.0 ft. West of fence corner

Original BT's: 48" Cedar N.78°E. 26 lks. (now stump).

All other bearing trees destroyed.

#41

86

1/4 Corner to Sections 10 and 15.

Post and Iron Pipe, set by single proportion.

Original BT's. destroyed.

New BT's: 10" Fir N.32°E. 23.45 ft. Mkd: 1/2 S RP BT.  
24" Fir S.12°W. 40.25 ft. Mkd: 1/2 S R P BT.

RE-RENEWED SEE CORNER NO. #181 = 87 SECTION CORNER NOT PROP. SET-BEE REN #40 THEREFORE 1/2 NOT RIGHT. C.S. FILE # 53/101

88

1/4 Corner between Section 10 and 9.

Post and Iron Pin - Original BT's: 6" Fir N.56°W. 25 lks., now 30".  
3" La. S.42°E. 15 lks. (stump).

117

Section Corner to Sections 9 - 10 - 15 - 16.

Post & Iron Pipe - 12" La. N.70°W. 53 lks., Original.

All other destroyed.

New BT's: 18" Cedar S.83 1/2°E. 13.5 ft. Mkd: T22S R5W S15 R P BT.  
24" Fir N.42 1/2°E. 20.0 ft. Mkd: T22S R5W S10 R P BT.  
32" Fir S. 7° W. 78.1 ft. Mkd: T22S R5W S16 R P BT.

89

B. H. McGillicuddy  
For-Whipple Lumber Co., Drain, Oregon  
April 1952  
R. M. File RM 1 - 40