

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 4 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

104

$\frac{1}{4}$ Corner to Sections 24 and 25.
Found - 36" Fir N.28°E. 21.8 ft., down, badly splintered 40" Fir. (Orig. BT)
40" Fir S.12°E. 12.9 ft., down, long butt moved by logging.
Haines "T" Iron in proper corner position.
BT's: - 70" Fir N.54°W. 23.0 ft. "W" Plate & Nail.
8" Hemlock S.7°W. 24.9 ft. "W" Nail & Plate.

Weyerhaeuser Co.
1959 - 1962
C. S. File No. 53/108

105

$\frac{1}{4}$ Corner to Sections 35 and 36.
Found - 50" Fir S.34°E. 5.9 ft., now 54" Fir with healed face.
36" Fir, now 40" Fir N.35°W. 5.9 ft., scribing visible (Orig. BT)
 $\frac{1}{2}$ " x 30" G.I.P. and 2" x 2" x 3" Fir Post.
BT's: - 14" Fir N.82°E. 24.1 ft. "W" Nail & Plate added.
40" Fir (Orig. BT) N.35°W. 4.0 ft. "W" Nail & Plate, added.

107

106

Section Corner to Secs. 17 - 18 - 19 - 20.
Found - 1 $\frac{3}{4}$ " Axle shaft, 14" above ground at Fence Corner N. & W.
N. E. BT., now stump pushed out of place.
Other BT's. recorded in Ren. #33 in good condition, as follows:
20" R. Fir S. 71° E. 46.9 ft., scribing visible.
20" R. Fir N. 69° W. 31.0 ft., scribing visible.
New BT's: 17" D. Fir S.84°W. 80.0 ft. Mkd: T23S R4W S19 CS BT.
8" R. Cedar N. 2° E. 262.0 ft. Mkd: T23S R4W S17 CSBT.

107

$\frac{1}{4}$ Corner to Sections 35 and 36.
Found - $\frac{1}{2}$ " I. Pipe, as recorded Ren. #105, now bent over.
New BT., down and dead.
Orig. 50", now 55" Fir S.34°E. 5.9 ft., open & find part of
a "B" scribe & reverse, Top broken out.
Orig. 36", now 40" Fir N.35°W. 5.9 ft., top broken out,
scribe visible on pitched over face.
New BT's: 8" D. Fir S.14°W. 22.0 ft. Mkd: $\frac{1}{2}$ S35 CS BT.
11" D. Fir S.79°E. 32.5 ft. Mkd: $\frac{1}{2}$ S36 CS BT.
Note - This corner lies on top of summit.

108

$\frac{1}{4}$ Corner to Sections 3 and 2.
Found - Haines' "T" Iron & Stumps of BT's. as recorded Ren. #55.
New BT's: 8" W. Oak S.47 $\frac{1}{2}$ °W. 105.3 ft. Mkd: $\frac{1}{2}$ S 3 CS BT.
No BT available in Sec. 2.
Note - This corner lies 13.5 ft. W. of N.-S. Fence.
Power pole bears S. 8° W. 25.7 feet.

109

Sec. Cor. to Secs. 7 & 18, T23-4W. & Secs. 12 & 13, T23-5W.
Found - $\frac{3}{4}$ " Iron Rod attached to fence corner course S. & E.
BT's. as recorded in Ren. #36, now snags.
All Orig. BT's now stump or turned out.
New BT's: 7" W. Fir N.33°W. 42.3 ft. Mkd: S12 CS BT.
7" W. Fir S.24°W. 51.2 ft. Mkd: S13 CS BT.
8" D. Fir S.22°E. 102.5 ft. Mkd: T23S R4W S18 CS BT.
No BT. available to N. E.

110

$\frac{1}{4}$ Cor. to Sec. 18, T23-4W. & Sec. 13, T23-5W.
Found - Brass Cap at Cor. as recorded Ren. #37, pushed out of place.
Orig. 50" Fir Snag still in place.
16" Cedar S.13 $\frac{1}{2}$ °E. 99.0 ft., now snag 10.0 ft. high, scribing
visible.
14" D. Fir N.35°W. 12.0 ft., alive, in fence corner, face
almost healed over, scribed high because of fence wire.
Reset Brass Cap and marked one new BT:
9" D. Fir N.18°E. 31.9 ft. Mkd: $\frac{1}{2}$ S18 CS BT.

Vernon "Ray" Tracy
Mike Stone & Jerry Layne
October 1965
C. S. File No. 54/16