

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 23 S T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C.S. File  
No  
54/16

Wilford N. Haiges  
For L. & H. Lumber Co.  
Sept/July, 1967  
Map File M 34 - 29

1/4 Corner to Sections 27 and 26. 145  
Found - Haines' "T" Iron & 3/4" I. P. at Cor., See Ren. #140.  
Orig. 24", now 48" D. Fir, N. 85° W. 27.7 ft., rebark scribed. Alive.  
Orig. 40", now badly decayed remnant of burned stump, S. 45° E. 2.0 ft.  
No scribe found.  
Haines' BT: 12", now 14" I. Cedar S. 69° E. 23.5 ft. scribed, with #185  
Haines' button on face. Cracked from ground up,  
beginning to rot.  
DO NOT SET BRASS CAP.  
New Bl's: 10" I. Cedar N. 54° W. 40.4 ft. mkd. 1/4 S27 CS BT.  
24" I. Cedar S. 49 1/2° E. 26.5 ft. mkd. 1/4 S26 CS BT.  
Note - This corner lies on S. slope of spur, course S.W.

Sept. 26, 1966

C.E. 1/16 Section 4. 146  
Found - "T" Iron 97.6 ft. E. of corner.  
Set - 5/8" Steel Rod, from which:  
Scribed: 12" Inc. Cedar S. 51° W. ?

S.E. 1/16 Corner Section 4. 147  
Found - "T" Iron, N. 87° 28' E. 90.2 ft. from corner and  
2 Trees which looked like BT's. Did not open.  
Set - 5/8" Steel Rod, from which:  
Scribed: 6" Fir N. 60° W. 12.6 ft.

July, 1967

MICROFILM TO HERE 10/67

V. R. Tracy  
& Crew  
9/19/68  
C.S. File  
No. 54/16

1/4 Corner to Sections 35 and 36. 148  
Found - 1/2" Iron Pipe for corner, See Ren. #107.  
(Alive) Orig. 50", now 55" Fir, S. 34° E. 5.9 ft., opened blaze, pitched over.  
Orig. 36", now 40" Fir, alive, N. 35° W. 5.9 ft., scribe visible.  
8" D. Fir S. 14° W. 22.0 ft., scribe visible on unhealed blaze.  
11" D. Fir S. 79° E. 32.5 ft., scribe visible on unhealed blaze.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 23 S R 4 W  
Office, 1968 1/4 S 35 | S 36  
This corner lies on top of summit. Reset I. P. alongside Brass Cap.

Sept. 19, 1968

MAR 71

1/4 Corner for Secs. 21 and 22. 149  
Set - Brass cap mkd. T23S, R4W, WM 1/4 S21, S22 1974 from which  
12" D. Fir, I scribed "1/4 S21 BT", bears N. 62 1/2° W., 52.6 ft. #181  
Rt. power pole, structure 1/76 PP&L pole No. 6517, bears  
S. 74 3/4° E., 32.3 ft.  
Lt. power pole, structure 1/76 PP&L pole No. 6504, bears  
S 67 1/2° E., 48.9 ft.

All tie bearings based on solar observation. No original evidence fd.

Section Corner For Secs. 21-22-28-27. 150

At the sec. cor. common to Secs. 21-22-27 & 28, T. 23S, R. 4W., W.M., which  
lies at the intersection of a very old North-South fence line, and an  
extension of a very old fence line from the West, and an old growth timber  
cutting line to the East, which point of intersection, according to  
witness Kathryn M. Howard, is to her knowledge the location of the  
original section corner.

Set - Brass cap mkd. T23S, R4W, WM S21, S22, S28, S27 1974  
from which - 8" D. Fir, I scribed "T23S, R4W S21 BT", bears N. 62° W., 45.9 ft.  
28" D. Fir, I scribed "T23S, R4W S22 BT", bears N. 88° E., 13.0 ft.  
28" D. Fir, I scribed "T23S, R4W S27 BT", bears S. 50° E., 18.7 ft.  
6" D. Fir, I scribed "T23S, R4W S28 BT", bears S 66° W., 43.1 ft.

No original BT's found.

2/14/74

Shaner Engineering  
for Pacific Power & Light Co.  
M 49 - 55  
Feb. 13, 1974

1976 BLM  
Restoration  
Feb. 7/90  
M10-41  
63/102  
63/104