

Douglas County Surveyor's Record of
Government Corners Renewed

T. 23 S. T. S. R. 7 W. R.W.W.M.

KOKE-CHAPMAN CO., EUREKA, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
July 1962
C. S. File No. 52/125

107

$\frac{1}{4}$ Corner to Sections 12 and 13.
Found - Fir, now 64", S.30°W. 33.7 ft., to face, plain bark
scribing visible " $\frac{1}{4}$ S BT". Tree dying. *See Ren #98*
Fir Stump, now 72", N.10°E. 19.1 ft. (to face) Plain
bark scribing visible " $\frac{1}{4}$ S" (lower part of stump buried in
dirt and debris).
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R7W $\frac{1}{4}$ S12
Office, 1962 S13
New BT's: 17" Yew S.68°E. 30.2 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
18" Hemlock N.16°W. 57.1 ft. Mkd: $\frac{1}{4}$ S12 CS BT.
Corner lies in old cat road approx. 60 ft. West of logging road and
approx. 80 ft. South of Creek.

108

Section Corner to Sections 11 - 12 - 13 - 14.
Found - Maple S.60°W. 25.7 ft., uprooted & down, one side rotted away.
Traces of reverse scribing visible. "BT" legible. *Ren #97*
Traces of rotten wood in stump hole N.10°W. 17.8 ft.
No trace of N.E. or S.E. BT's. in old cat road.
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R7W S11 | S12 #172
Office, 1962 S14 | S13
New BT's: 20" W. Fir N.53°W. 46.2 ft. Mkd: T23S R7W S11 CS BT.
12" R. Cedar S.58°W. 59.1 ft. Mkd: T23S R7W S14 CS BT.
12" Maple S.66°E. 125.4 ft. Mkd: T23S R7W S12 CS BT.
16" R. Cedar S.72 $\frac{1}{2}$ °E. 182.2 ft. Mkd: T23S R7W S13 CS BT.
Corner lies in small draw running East, about 60 ft. West of logging road.

RE-RENEWED CORNER NO.

109

Witness Corner to meander corner to Sections 32 and 33.
Found - Brass Cap set Previously. *Ren #77*
8" Fir S.52 $\frac{1}{2}$ °E. 176.9 ft. scribing still visible. This tree
is to be removed for road construction. *Fd. by: Don Banta 3/83*
S. W. Bearing Tree is gone. *M 90-38 A 15*
New BT's: 9" D. Fir S.53°W. 77.6 ft. Mkd: "W.C. M.C. S32 CS BT".
9" Myrtle S.69°E. 268.0 ft. Mkd: "W.C. M.C. S33 CS BT".
Did not move brass cap at Wit. Cor. It did not appear to
be in danger of being disturbed.

August 14, 1962

110

Closing Corner Section 6 & 5, T24-7W.
South Line Sec. 31, T23S-R7W.
Found - Stump hole & pieces of badly burned Fir Stump S12°E. 17.2 ft. No Mks.
No trace of S.W. BT. Point for corner falls 152.3 ft. due West of
corner of Sections 31 and 32, T23S R7W, (gov't. notes call for closing corner
2.30 chains, (151.8 ft.) West of corner. Secs. 31 and 32). Since location
is so close to call from Orig. corner, I conclude stump hole was SE. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R7W C C S 6 / S5
New BT's: 18" D. Fir S.20°E. 11.1 ft. Mkd: T24S R7W C S 5 CS BT
14" D. Fir S.39°W. 82.3 ft. Mkd: T24S R7W C C S 6 CS BT.
A $\frac{3}{4}$ " Iron Pipe bears N. 68° E. 2.3 feet.

111

$\frac{1}{4}$ Section Corner common to Sections 26 and 25.
Found - 20" Maple S.80°W. 35.6 ft., opened & fd. good scribing "BT". *Ren #42*
18" Dogwood S.30°E. 19.8 ft., part of old face visible, badly
rotted, part of "S" visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T23S R7W $\frac{1}{4}$ S26/S25
New BT's: 53" D. Fir N.60°E. 78.3 ft. Mkd: $\frac{1}{4}$ S25 CS BT.
15" Red Cedar N.27°W. 96.7 ft. Mkd: $\frac{1}{4}$ S26 CS BT.
Note - Corner lies on very steep north slope.

Milo E. Godfrey
& Crew
March 23, 1964
C. S. File
No. 52/125