

Douglas County Surveyor's Record of  
Government Corners Renewed

T 23 T. S. R 7 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 97501

146

Meander Corner for Secs. 4 and 3, T24-7  
Set - 5/8" x 30" Rebar in rip-rap at edge County Road.  
BT's - 21" Myrtle, S.67°E., 53.2 ft. "T24S R7W S3 MC BT".  
15" Myrtle, N.29°W., 17.6 ft. "T24S R7W S4 MC BT".  
Corner is 22 ft. from travelled center line County Road, Top of  
river bank 69 ft. north.

**RE-RENEWED, SEE CORNER NO. #158**

William Eimstadt  
For: International Paper  
July 1976  
M 61 - 14

147

Meander Corner Sections 33 and Sec. 4, T24-7  
Set - 5/8" x 30" Rebar at corner.  
BT's - 40" Grand Fir, N.52°W., 42.3 ft. "T23S R7W S33 MC BT".  
18" Maple, S.36°E., 14.0 ft. "T24S R7W S4 MC BT".  
Center line road 57.7 ft. West - Top river bank 53 ft. East.

**RE-RENEWED, SEE CORNER NO. #157**

148

South 1/4 Corner for Sec. 33 only.  
Set - 5/8" x 30" Rebar at corner.  
BT's - 24" Fir, N.52°50' W., 22.3 ft. "1/4 S33 BT".  
28" Fir, N.32 1/4°E., 35.8 ft. "1/4 S33 BT".

149

North 1/4 Corner for Sec. 4 only, T24-7  
Set - 5/8" x 30" Rebar at corner.  
BT's - 32" Fir, S.12°E., 41.9 ft. "1/4 S4 BT".  
6" Grand Fir, S.25°W., 24.2 ft. "1/4 S4 BT".

**RE-RENEWED, SEE CORNER NO. #156**

7/76

3/77

Township corner for Sec. 36; and Sec. 31 of T23-6; Sec. 1 of T.24-7  
and Sec. 6 of T24-6. 150

Found - All evidence of the orig. corner is gone.  
Found a BLM brass cap reset by unknown party approx. 0.5 ft. from  
proper location. This cor. was referenced by Doug. Co. Surveyors  
Office in 1972 for road construction per notes attached to field  
notes this renewal.  
Found a 5/8" I.R. and PK nail in stump established as refereces for  
this corner, N.84 1/2°E.  
The SE references have been destroyed.  
We RESET the BLM brass cap at the proper location as determined by transit and  
chain from the County Surveyors references  
Found - From the 1957 dependent resurvey, a 22" now 23" G.Fir with well healed  
blaze bears N.74 1/2°W., 115.6 ft. (Rec. 116.8 ft.)  
The NE bearing tree has been destroyed.  
From the 1964 BLM resurvey correcting the 1957 dependent resurvey:  
An 8" now 12" D. Fir alive with well healed single blaze bears  
N.63°E., 73.3 ft.  
and a 15" now 17" F. Cedar with scribing "S R6W S6" visible on  
partially healed single blaze bears S.85°E., 107.6 ft.  
RESET the BLM iron post with brass cap attached marked as described in the  
official record, flush in the shouldr of a dirt logging road.  
We add the markings "Reset 1977" to the B.C.  
No new accessories. We place steel fence post with survey marker witness  
sign attached approx. one foot west of brass cap.

**RE-RENEWED, SEE CORNER NO. #177**

Gary L. Langlitz, Doug. Co. Surveyors  
Office  
R. B. Kimberling - M. W. Cline  
Aug. 29, 1977  
C.S. 59/38

8/29/77

151

Section Corner for Secs. 7, 8, 18 and 17.  
Found - A 2 1/2" I.P. with 1965 GLO brass cap. Cap was covered with two  
feet loose shale, Cap located on steep slide area. This corner is  
continuously buried by loose shale.  
A fir, 5" now a 12" bent Fir, bears N.47°E., 90.4 ft. with healed  
over single blaze.  
A 17" now 20" Fir, bears S.63 1/2°E., 81.8 ft. with healed over  
double blaze.  
An Alder, 7" now 12" bears N.12 1/2°W., 77.9 ft. with healed over  
double blaze. (1965 resurvey)  
A 12" Fir, bears S.40 1/2°W., 23.1 ft. with healed over double  
blaze. Ren. #13

Gary Langlitz  
Karen Reed  
Frank Silagy  
Doug. Co. Surveyors  
Office  
Nov. 28, 1978  
C.S. 60/17

Original Fir snag not found.  
Set - Left cap in position.  
B.O. - Marked rock bluff with "B O T" which bears N.86°W., 39.8 ft.  
Letters and "+" approx. 6 ins. tall.

Note - Corner falls in middle of slide in loose shale.

11/28/78

1-79