

Douglas County Surveyor's Record of
Government Corners Renewed

T 23 T. S. R 9 R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 91881

Michael S. McDowell
For: Weyerhaeuser
Company
Dec. 1, 1976
M 62 - 48
C.S. 58/128

NE Corner for Sec. 36, T23-10
Set - 2" Gal. I.P. with brass cap
From Which:

- A 12" Chinquapin, scribed BT, bears N.57°W., 16.7 ft.
- A 10" Chinquapin, scribed BT, bears S.41°E., 9.6 ft.
- A 10" Fir, scribed BT, bears S.87°W., 15.2 ft.
- A 14" Fir, scribed BT, bears N.35°W., 11.2 ft.

Dec. 1, 1976

FIND. OF 5/91
M 113-34 AFB

SW Corner Sec. 32 only.

Found - 3/4" Gal. I.P. placed by Weyerhaeuser Co. engineers in 1974 (unrecorded)

From Which:

- a 18" Fir stump (OBT) scar evident, bears N.40°E., 9.9 ft.
- a 36" Fir windfall (OBT) face evident bears N.53°W., 33.0 ft.
- a 12" Chinquapin RP bears N.76° 30'E., 19.9 ft.
- a 12" Fir RP bears S.15°30'E., 19.8 ft.
- a 8" Fir RP bears S.52°W., 6.8 ft.
- a 8" Fir RP bears N.81°W., 27.6 ft.

E. 1/4 Corner Section 31.

THIS CORNER SET IN ERROR - SEE LETTER DATED 4/12/78 IN C.S. FILE 58/139.

Set - 1 1/2" Gal. I.P. with brass cap, from Which:

- BT's - a 48" Fir stump BT, bark scribed, bears S.48°30'W., 53.6 ft.
- a 36" Fir stump RP bears S.31°30'E., 37.1 ft.

NE Corner Sec. 31.

THIS CORNER SET IN ERROR SEE LETTER DATED 4/12/78 IN C.S. FILE 58/139

Set - 1 1/2" Gal. I.P. with brass cap, from Which:

- BT's - a 6" Fir BT, scribed, bears S.57°30'W., 43.2 ft.
- a 4" Fir BT, scribed bears N.35°W., 22.4 ft.

NW Corner Section 32.

THIS CORNER SET IN ERROR SEE LETTER DATED 4-12-78 IN C.S. FILE 58/139

Set - 1 1/2" Gal. I.P. with brass cap, from Which:

- BT's - a 4" Fir BT, scribed, bears N.04°E., 33.0 ft.
- a 42" Fir BT, bark scribed, bears S.16°E., 92.5 ft.

Section Corner for Secs. 3,4, 9 and 10.

(Dec. 28, 1977)

Found - 3/4" I. Pipe without cap.

- 48" Fir stump N.10°E., 29.7 ft. no scribing
- 24" double bottom Fir stump N.46°W., 13.2 ft. scribed BT.
- 10" Fir stump, uprooted, scribed as described by County Surveyor 10/9/73 as 10" Hemlock S.66°W., 50.4 ft. Ren. #69
- 36" Fir stump S.89°W., 36.1 ft. no scribing.

Set - 1 1/2" x 30" pipe with 2 1/2" brass cap marked: T23S R9W W.M.

4 | 3
9 | 10
Sec Cor 1977 PLS 1374

January 4, 1978

BT's rescribed:

- 48" Fir stump N.10°E., 29.7 ft. scribed T23S R9W S3 BT.
- 24" Double bottom Fir stump N.46°W., 13.2 ft. scribed T23S R9W S4 BT
- 36" Fir stump S.89°W., 36.1 ft. scribed T23S R9W S9 BT.
- New BT - 36" Fir stump S.47°E., 45.5 ft. scribed T23S R9W S10 BT.

12/77 & 1/4/78

East 1/4 Corner for Sec. 31.

Set - A 1 1/2" Gal. I.P. with brass cap.

BT's- No live trees of sufficient size available for bearing trees. Referenced the following partially rotted stumps with tags & Gal. spikes but did not scribe;

- A 48" Fir stump S.18°E., 23.2 ft.
- A 48" Fir stump S.60°W., 56.6 ft.

Ren. #79 and following notation.

(Partial content of letter dated April 12, 1978 to Doug. Co. Surveyor from Weyerhaeuser: "We have destroyed all accessories to the corners we set as well the East 1/4 corner of Section 31. Enclosed is a plat for the corrected position of the East 1/4 corner of Section 31, based on the cadastral location of the Northeast corner and latest GLO record distances and bearings.")

(Renewals #'s80 and 81) See M 63 - 23 for orig. Weyerhaeuser map and C.S. 58/139 for replacement.

4/12/78

Michael S. McDowell
For: Weyerhaeuser Company
February 21, 1977
M 63 - 23 C.S. 58/139

Stephen D. Waite
LS #1374
For: International
Paper
12/28/77 and
1/4/78
C.S. 58/159

77

78

79

80

81

82

83